



ALLIANCE

Environmental Group, Inc.

THE BEST ENVIRONMENTAL SOLUTION

GREATER CLARK COUNTY SCHOOLS

AUTO TECH PROGRAM/WITTEN PROPERTY

AHERA

ASBESTOS MANAGEMENT PLAN

**DESIGNATED PERSON
TRUTH AND CORRECT STATEMENT**

Local Education Agency – Greater Clark County Schools
2112 Utica-Sellersburg Road
Jeffersonville, Indiana 47130

Designated Person - Alliance Environmental Group, Inc.
Sandra Shadley
5153 Commerce Square Drive, Suite E
Indianapolis, Indiana 46237

This Truth and Correct Statement, as outlined in 40 CFR 763.93(i), certifies that the general, local education agency responsibilities, as stipulated by 40 CFR 763.84, have been or will be met. These responsibilities include:

1. Ensure that the activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with 40 CFR 763 Subpart E.
2. Ensure all custodial and maintenance employees are properly trained as required by 40 CFR 763 Subpart E and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration Asbestos Standard for Construction, the EPA Worker Protection Rule, or applicable State regulations).
3. Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress.
4. Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.
5. Ensure that warning labels are posted in accordance with Section 763.95.
6. Ensure management plans are available for inspection and notification of such availability has been provided as specified in the management plan under Section 763.93(g).
7. The undersigned person designated by the LEA pursuant to Section 763.84(g) (1) has received adequate training as stipulated in Section 763.84(g) (2).
8. The LEA has and will consider whether any conflict of interest may arise from the interrelationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under Part 763.

Signature:  Date: November 6, 2016

Sandra S. Shadley

ASBESTOS PROGRAM MASTER INDEX

The following volumes are part of the Asbestos Program for the

GREATER CLARK COUNTY SCHOOLS

AUTO TECH PROGRAM/WITTEN PROPERTY

- A. Original Asbestos Management Plan for each school building.
- B. Asbestos Management Plan Supplement for each school building.
 - 1. Amendments to Management Plan
 - 2. Remaining Material Report
 - 3. Surveillance and Reinspection information
 - 4. Notices, Accreditation and Training Records
 - 5. Operations and Maintenance Records
 - 6. Asbestos Removal Projects
 - 7. Short Term Removal Information
 - 8. Original Inspection and Architect Statement

Copies of both volumes are found in the respective buildings. The Administration Building also contains duplicate copies of each volume for each school in its entirety.

SECTION 1

AMENDMENTS TO MANAGEMENT PLAN

SECTION 2

REMAINING MATERIAL REPORTS

Greater Clark County School Corporation

Remaining Materials Report

4/23/2020

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

1/14/2020

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

1/14/2020

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

5/16/2019

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

11/13/2018

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

5/2/2018

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

10/18/2017

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

4/13/2017

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

11/3/2016

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

4/28/2016

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County School Corporation

Remaining Materials Report

10/20/2015

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>Auto Tech</u>						
CB	Cove Base	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CBM	Cove Base Mastic	131	LF	Assumed	Office, Foyer, Classrooms and Restroom	O&M
CS	Ceiling Stipple	390	SF	Assumed	Foyer, Office & Restrooms	O&M
CT	2' X 2' Ceiling Tile	1116	SF	Assumed	Classroom	O&M
DW	Drywall	Unquantified	SF	Assumed	Throughout	O&M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171	SF	Assumed	Foyer & small restroom off of auto bay/garage area	O&M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60	SF	Assumed	Large restroom by classroom	O&M
FTM	Floor tile mastic	231	SF	Assumed	Foyer and restrooms	O&M

Greater Clark County Schools
Remaining Materials Report
April 22, 2015

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CBM	Cove Base Mastic	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60 SF	A	Large restroom by classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

**Greater Clark County Schools
Remaining Materials Report
October 22, 2014**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CBM	Cove Base Mastic	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60 SF	A	Large restroom by classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

**Greater Clark County Schools
Remaining Materials Report
October 22, 2014**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CBM	Cove Base Mastic	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60 SF	A	Large restroom by classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

**Greater Clark County Schools
Remaining Materials Report
December 15, 2011**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CBM	Cove Base Mastic	131 LF	A	Office, Foyer, Classrooms and Restroom	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink (older)	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink (new)	60 SF	A	Large restroom by classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

**Greater Clark County Schools
Remaining Materials Report
June 27, 2011**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office & Foyer	O & M
CBM	Cove Base Mastic	131 LF	A	Office & Foyer Area	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink	60 SF	A	Large restroom in classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

**Greater Clark County Schools
Remaining Materials Report
June 27, 2011**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>Auto Tech Program/Witten Property</u>					
CB	Cove Base	131 LF	A	Office & Foyer	O & M
CBM	Cove Base Mastic	131 LF	A	Office & Foyer Area	O & M
CS	Ceiling Stipple	390 SF	A	Foyer, Office & Restrooms	O & M
CT	2' X 2' Ceiling Tile	1116 SF	A	Classroom	O & M
DW	Drywall	Unquantified SF	A	Throughout	O & M
FT1	12" X 12" Floor tile off white w/blue & pink	171 SF	A	Foyer & small restroom off of auto bay/garage area	O & M
FT2	12" X 12" Floor Tile off white w/ blue & pink	60 SF	A	Large restroom in classroom	O & M
FTM	Floor tile mastic	231 SF	A	Foyer and restrooms	O & M

SECTION 3

SURVEILLANCE AND REINSPECTION INFORMATION

1. Periodic surveillance and Reinspection schedules
2. Reports, by homogeneous areas for Periodic Surveillance and Reinspections.
3. Results of additional bulk sample collected, if any, during periodic surveillance.

SURVEILLANCE INFORMATION

PERIODIC SURVEILLANCE PLAN

GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each re-inspection will be maintained in this binder.

DATE PLANNED	DATE COMPLETED	COMPLETED BY
<u>October 2014</u>	October 22, 2014	Benjamin B
<u>April 2015</u>	April 22, 2015	Benjamin B
<u>October 2015</u>	October 20, 2016	Benjamin B
<u>April 2016</u>	RE-INSPECTION	Benjamin B
<u>October 2016</u>	November 3, 2016	DATE
<u>April 2017</u>	April 13, 2017	Jamie A. Hester
<u>October 2017</u>	October 18, 2017	DATE
<u>April 2018</u>	May 2, 2018	Benjamin B
<u>October 2018</u>	November 13, 2018	Benjamin B
<u>April 2019</u>	RE-INSPECTION	SC
<u>October 2019</u>	January 14, 2020	Mel B
<u>April 2020</u>	April 23, 2020	Mel B
<u>October 2020</u>		

SURVEILLANCE INFORMATION

PERIODIC SURVEILLANCE PLAN

GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each re-inspection will be maintained in this binder.

<u>April 2021</u>	<hr/>	<hr/>
<u>October 2021</u>	<hr/>	<hr/>
<u>April 2022</u>	RE-INSPECTION	<hr/>
<u>October 2022</u>	<hr/>	<hr/>
<u>April 2023</u>	<hr/>	<hr/>
<u>October 2023</u>	<hr/>	<hr/>
<u>April 2024</u>	<hr/>	<hr/>
<u>October 2024</u>	<hr/>	<hr/>
<u>April 2025</u>	RE-INSPECTION	<hr/>
<u>October 2025</u>	<hr/>	<hr/>
<u>April 2026</u>	<hr/>	<hr/>
<u>October 2026</u>	<hr/>	<hr/>

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CB

HA Description Cove Base

HA Type Miscellaneous Material

HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CS

HA Description Ceiling Stipple

HA Type Surfacing Material

HA Location Foyer, Office & Restrooms

Quantity 390 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/23/2020


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector 

Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CS

HA Description Ceiling Stipple

HA Type Surfacing Material

HA Location Foyer, Office & Restrooms

Quantity 390 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector 

Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CS

HA Description Ceiling Stipple

HA Type Surfacing Material

HA Location Foyer, Office & Restrooms

Quantity 390 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/13/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment


Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CS
HA Description Ceiling Stipple
HA Type Surfacing Material
HA Location Foyer, Office & Restrooms

Quantity 390 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration


Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment


Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CS
HA Description Ceiling Stipple
HA Type Surfacing Material
HA Location Foyer, Office & Restrooms

Quantity 390 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No
Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector 

Dustin Hawkins

State IN
Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CS
HA Description Ceiling Stipple
HA Type Surfacing Material
HA Location Foyer, Office & Restrooms

Quantity 390 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None
<u>Planned Response Action</u>	O&M	

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CS

HA Description Ceiling Stipple

HA Type Surfacing Material

HA Location Foyer, Office & Restrooms

Quantity 390 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID DW

HA Description Drywall

HA Type Miscellaneous Material

HA Location Throughout

Quantity Unquantified SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CS
HA Description Ceiling Stipple
HA Type Surfacing Material
HA Location Foyer, Office & Restrooms

Quantity 390 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector 
Benjamin S. Hood

State IN
Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom

Material Description
Cove Base

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom

Material Description
Cove Base Mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF

Material Location
Foyer, Office & Restrooms

Material Description
Ceiling Stipple

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M




Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name	Greater Clark County Schools	
Building Name	Auto Tech Program/Witten Property	
HA#	CT	
Type of Material	Miscellaneous Material	
Quantity of Material	1116 SF	
Material Location	Classroom	
Material Description	2' X 2' Ceiling Tile	
Comments	This material overall was not in poor condition.	
Does Material Contain Asbestos?	Assumed	
Is it Friable?	Yes	
Original Inspection Date	6/27/2011	
Current Surveillance Date	4/22/2015	
Current Assessment Rating	NA	Not Applicable
Cause of Damage	No Damage	
Accessible	Yes	
Potential for Damage	Low	
Removed	No	
Planned Response Action	O & M	



Inspector

Benjamin S. Hood

State	Indiana
Accreditation Number	19A001039


PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# DW
Type of Material Miscellaneous Material
Quantity of Material Unquantified SF
Material Location
Throughout
Material Description
Drywall

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage L
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area


Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF

Material Location
Large restroom by classroom

Material Description
12" X 12" Floor Tile off white w/ blue & pink (new)

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FTM
Type of Material Miscellaneous Material
Quantity of Material 231 SF

Material Location
Foyer and restrooms

Material Description
Floor tile mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/22/2015
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M




Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF
Material Location
Office, Foyer, Classrooms and Restroom
Material Description
Cove Base
Comments
This material overall was not in poor condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom

Material Description
Cove Base Mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039


PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF
Material Location
Foyer, Office & Restrooms

Material Description
Ceiling Stipple

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name	Greater Clark County Schools
Building Name	Auto Tech Program/Witten Property
HA#	CT
Type of Material	Miscellaneous Material
Quantity of Material	1116 SF
Material Location	Classroom
Material Description	2' X 2' Ceiling Tile
Comments	This material overall was not in poor condition.
Does Material Contain Asbestos?	Assumed
Is it Friable?	Yes
Original Inspection Date	6/27/2011
Current Surveillance Date	10/22/2014
Current Assessment Rating	NA Not Applicable
Cause of Damage	No Damage
Accessible	Yes
Potential for Damage	Low
Removed	No
Planned Response Action	O & M

Inspector


Benjamin S. Hood

State

Indiana

Accreditation Number

19A001039


PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# DW
Type of Material Miscellaneous Material
Quantity of Material Unquantified SF
Material Location
Throughout
Material Description
Drywall

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage L
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area


Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF

Material Location
Large restroom by classroom

Material Description
12" X 12" Floor Tile off white w/ blue & pink (new)

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 10/22/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M




Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name	Greater Clark County Schools	
Building Name	Auto Tech Program/Witten Property	
HA#	FTM	
Type of Material	Miscellaneous Material	
Quantity of Material	231 SF	
Material Location	Foyer and restrooms	
Material Description	Floor tile mastic	
Comments	This material overall was not in poor condition.	
Does Material Contain Asbestos?	Assumed	
Is it Friable?	No	
Original Inspection Date	6/27/2011	
Current Surveillance Date	10/22/2014	
Current Assessment Rating	NA	Not Applicable
Cause of Damage	No Damage	
Accessible	Yes	
Potential for Damage	Low	
Removed	No	
Planned Response Action	O & M	



Inspector

Benjamin S. Hood

State	Indiana
Accreditation Number	19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom

Material Description
Cove Base

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom

Material Description
Cove Base Mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF
Material Location
Foyer, Office & Restrooms

Material Description
Ceiling Stipple

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Jeffrey P. Rechtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CT
Type of Material Miscellaneous Material
Quantity of Material 1116 SF
Material Location
Classroom
Material Description
2' X 2' Ceiling Tile

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? Yes
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name	Greater Clark County Schools	
Building Name	Auto Tech Program/Witten Property	
HA#	DW	
Type of Material	Miscellaneous Material	
Quantity of Material	Unquantified SF	
Material Location	Throughout	
Material Description	Drywall	
Comments	This material overall was not in poor condition.	
Does Material Contain Asbestos?	Assumed	
Is it Friable?	No	
Original Inspection Date	6/27/2011	
Current Surveillance Date	4/21/2014	
Current Assessment Rating	NA	Not Applicable
Cause of Damage	No Damage	
Accessible	Yes	
Potential for Damage	L	
Removed	No	
Planned Response Action	O & M	
Inspector	 _____ Jeffrey P. Rechten	
State	Indiana	
Accreditation Number	19A003594	

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area

Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF

Material Location
Large restroom by classroom

Material Description
12" X 12" Floor Tile off white w/ blue & pink (new)

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FTM
Type of Material Miscellaneous Material
Quantity of Material 231 SF

Material Location
Foyer and restrooms

Material Description
Floor tile mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 4/21/2014
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF
Material Location
Office, Foyer, Classrooms and Restroom
Material Description
Cove Base

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office, Foyer, Classrooms and Restroom


Material Description
Cove Base Mastic

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF
Material Location
Foyer, Office & Restrooms
Material Description
Ceiling Stipple

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CT
Type of Material Miscellaneous Material
Quantity of Material 1116 SF
Material Location
Classroom
Material Description
2' X 2' Ceiling Tile

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? Yes
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# DW
Type of Material Miscellaneous Material
Quantity of Material Unquantified SF
Material Location
Throughout
Material Description
Drywall

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage L
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area

Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF

Material Location

Large restroom by classroom

Material Description


12" X 12" Floor Tile off white w/ blue & pink (new)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State

Indiana

Accreditation Number

19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FTM
Type of Material Miscellaneous Material
Quantity of Material 231 SF


Material Location
Foyer and restrooms

Material Description
Floor tile mastic

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Surveillance Date 12/15/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF
Material Location
Office & Foyer
Material Description
Cove Base

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF
Material Location
Office & Foyer Area
Material Description
Cove Base Mastic

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF
Material Location
Foyer, Office & Restrooms
Material Description
Ceiling Stipple

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CT
Type of Material Miscellaneous Material
Quantity of Material 1116 SF
Material Location
Classroom
Material Description
2' X 2' Ceiling Tile

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? Yes
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# DW
Type of Material Miscellaneous Material
Quantity of Material Unquantified SF
Material Location
Throughout
Material Description
Drywall
Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage L
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area

Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State

Indiana

Accreditation Number

19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF

Material Location

Large restroom in classroom

Material Description


12" X 12" Floor Tile off white w/ blue & pink (new)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FTM
Type of Material Miscellaneous Material
Quantity of Material 231 SF
Material Location
Foyer and restrooms
Material Description
Floor tile mastic
Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

THIRD YEAR REINSPECTIONS

REINSPECTION PLAN**GREATER CLARK COUNTY SCHOOLS**

Reinspection by an accredited building inspector will be scheduled to be performed not more than three years from the date of the original inspection. The reinspection report will then be made a permanent part of this Management Plan. Reinspections will be performed every three years for as long as the building contains ACBM, and will be reinspected once within three years from the date that all ACBM has been removed.

Records of each reinspection should be maintained in this binder.

DATE PLANNED**DATE COMPLETED****COMPLETED BY**

<u>JUNE 2007</u>	<u>July 2007</u>	<u>Bill Ogle</u>
<u>JUNE 2010</u>	<u>June 2010</u>	<u>Sandy Shadley</u>
<u>JUNE 2013</u>	<u>April 2013</u>	<u>Jeff Hechtin</u>
<u>JUNE 2016</u>	<u>April 28, 2016</u>	<u>Brian</u>
<u>JUNE 2019</u>	<u>May 16, 2019</u>	<u>SG</u>
<u>JUNE 2022</u>	<u></u>	<u></u>
<u>JUNE 2025</u>	<u></u>	<u></u>

Triennial Reinspection

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CB

HA Description Cove Base

HA Type Miscellaneous Material

HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CS

HA Description Ceiling Stipple

HA Type Surfacing Material

HA Location Foyer, Office & Restrooms

Quantity 390 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID CT

HA Description 2' X 2' Ceiling Tile

HA Type Miscellaneous Material

HA Location Classroom

Quantity 1116 SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable Yes

Original Inspection 6/27/2011

Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation

Building Name Auto Tech

Building Number 29

HA ID DW

HA Description Drywall

HA Type Miscellaneous Material

HA Location Throughout

Quantity Unquantified SF

Comments This material overall was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 6/27/2011

Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CB
HA Description Cove Base
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CBM
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Office, Foyer, Classrooms and Restroom

Quantity 131 LF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CS
HA Description Ceiling Stipple
HA Type Surfacing Material
HA Location Foyer, Office & Restrooms

Quantity 390 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition	
<u>Physical Contact</u>		<u>Vibration</u>	<u>Air</u>
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID CT
HA Description 2' X 2' Ceiling Tile
HA Type Miscellaneous Material
HA Location Classroom

Quantity 1116 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable Yes

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID DW
HA Description Drywall
HA Type Miscellaneous Material
HA Location Throughout

Quantity Unquantified SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT1
HA Description 12" X 12" Floor tile off white w/blue & pink (older)
HA Type Miscellaneous Material
HA Location Foyer & small restroom off of auto bay/garage area

Quantity 171 SF
Comments This material overall was not in poor condition. Minor chipping/cracking at the threshold of foyer and garage.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FT2
HA Description 12" X 12" Floor Tile off white w/ blue & pink (new)
HA Type Miscellaneous Material
HA Location Large restroom by classroom

Quantity 60 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name Auto Tech
Building Number 29
HA ID FTM
HA Description Floor tile mastic
HA Type Miscellaneous Material
HA Location Foyer and restrooms

Quantity 231 SF
Comments This material overall was not in poor condition.
Asbestos Assumed
Friable No

Original Inspection 6/27/2011
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

<u>Percent Damaged</u>	%	Good Condition
<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

SECTION 4

NOTICES, ACCREDITATION AND TRAINING RECORDS

1. Annual notice log
2. Maintenance and Custodial staff training log
3. O & M and inspection personnel training certificates
4. LEA Designated Person training certificates
5. Other school personnel training certificates

Indiana Department of Environmental Management
100 N. Senate Avenue
Mail Code 61-52 IGCN 1003
Indianapolis, IN 46204-2251



April 17, 2014

RECEIVED APR 22 2014

Benjamin S. Hood
Alliance Environmental Group
5340 Commerce Circle, Ste E
Indianapolis IN 46237

Re: Asbestos Inspector # 19A001039

Based upon the review of your license application, the Office of Air Quality has determined that you have fulfilled the requirements of 326 IAC 18 and are eligible for licensing in the following discipline:

Asbestos Inspector

Your Asbestos Inspector license is attached below. The license is waterproof and tear resistant. Please sign your license and do not laminate or alter your license in anyway. Your license must be available for review at all times while implementing an asbestos project. This license may be revoked, pursuant to 326 IAC 18-1-7, if you:

- (1) Violate any requirements of these rules (326 IAC 18), 326 IAC 14-10, or any requirement of the Asbestos-Containing Materials in Schools Rule or any other federal, state, or local regulation pertaining to asbestos in buildings or to asbestos projects.
- (2) Falsify information on your application for licensing.
- (3) Fail to meet any qualifications specified in 326-IAC 18-1-4.
- (4) Conduct asbestos project, or related asbestos handling activity, in a manner which is hazardous to the public health.

Your license is valid effective 05/05/2014, and will expire on 05/05/2015, as indicated on your card. We suggest that you attend the required training and submit an application for license renewal early to insure your license does not lapse. NOTE: 326 IAC 18-1-4(h) and 326 IAC 18-1-6(e) require that any individual who has an eighteen (18) month lapse between any two training courses of the same discipline to attend an initial training course for the discipline in which they are seeking a license. In order to avoid re-taking the initial training course you must have attended a refresher in the discipline you are seeking a license within eighteen (18) months from the date of issuance of your last training course certificate.

Office of Air Quality, Asbestos Licensing Section (317) 233-3861



Indiana Dept. of Environmental Management

Benjamin S. Hood

Asbestos Inspector License #: 19A001039

Effective: 05/05/2014	Expiration: 05/05/2015
Birth Date: 04/10/1978	Gender: M
Height: 6-00	Eye Color: Brown
Weight: 285	Hair Color: Brown

AHERA NOTIFICATION LOG

GREATER CLARK COUNTY SCHOOLS

DATE OF NOTIFICATION

COPY IN BOOK

YEAR

2011



2012



2013



2014



2015



2016

2017

2018

2019

2020

2021

2022

2023

2024

March 2015

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services at River Valley Middle School, which is located at 2220 Veteran's Parkway, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, Service Center, Corden Porter Storage, Auto Tech Program- Witten Property, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2015/2016 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

* The required triennial re-inspection will be performed in April 2016.

* The required six month periodic surveillance was performed in October 2014.

* The required six month periodic surveillance activities are scheduled for April and October each year.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

March 2014

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2220 Veteran's Parkway, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, Corden Porter Storage, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2014/2015 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

* The required triennial re-inspection will be performed in April 2013.

* The required six month periodic surveillance was performed in October 2013.

* The required six month periodic surveillance activities are scheduled for April and October each year.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

March 2013

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, Corden Porter Storage, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2013/2014 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

- * The required triennial re-inspection will be performed in April 2013.
- * The required six month periodic surveillance was performed in October 2012.
- * The required six month periodic surveillance activities are scheduled for April and October each year.
- * Projects completed in 2012: Parkview Middle School.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

March 2012

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, and Cordon Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2012/2013 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

- * The required triennial re-inspection will be performed in June 2013.
- * The required six month periodic surveillance was performed in December 2011.
- * The required six month periodic surveillance activities are scheduled for June and December each year.
- * Projects completed in 2011: Options building and Parkwood Elementary.
- * Projects scheduled for 2012: Parkview Middle School and Bridgepoint Elementary.
- * Cordon Porter storage building was sold in 2012.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxillary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, Options and Corden Porter Center Buildings and Alternative School-

- * The required triennial reinspection will be performed in June 2013.
- * The required six month periodic surveillance was performed in December 2010.
- * The next scheduled activity is the required six month periodic surveillance in June 2011.
- * Charlestown High School asbestos removal project was completed in 2010.
- * Options Building is under renovation in 2011.
- * Parkwood Elementary is under renovation in 2011.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building
– These buildings are asbestos free and **Riverside Elementary** was demolished in 2006.
No surveillances or reinspections are required for these buildings.

March 2011

SECTION 5

OPERATIONS AND MAINTENANCE RECORDS

SECTION 6

ASBESTOS REMOVAL PROJECTS

SECTION 7

SHORT TERM WORKER INFORMATION

SECTION 8

Original Inspection and Architect Statement

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CB
Type of Material Miscellaneous Material
Quantity of Material 131 LF

Material Location
Office & Foyer


Material Description
Cove Base

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CBM
Type of Material Miscellaneous Material
Quantity of Material 131 LF
Material Location
Office & Foyer Area
Material Description
Cove Base Mastic

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CS
Type of Material Surfacing Material
Quantity of Material 390 SF
Material Location
Foyer, Office & Restrooms
Material Description
Ceiling Stipple

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT


LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# CT
Type of Material Miscellaneous Material
Quantity of Material 1116 SF
Material Location
Classroom
Material Description
2' X 2' Ceiling Tile

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? Yes
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# DW
Type of Material Miscellaneous Material
Quantity of Material Unquantified SF

Material Location
Throughout

Material Description
Drywall

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage L
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT1
Type of Material Miscellaneous Material
Quantity of Material 171 SF

Material Location

Foyer & small restroom off of auto bay/garage area

Material Description

12" X 12" Floor tile off white w/blue & pink (older)

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State

Indiana

Accreditation Number

19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FT2
Type of Material Miscellaneous Material
Quantity of Material 60 SF


Material Location
Large restroom in classroom

Material Description
12" X 12" Floor Tile off white w/ blue & pink (new)

Comments
This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

ORIGINAL INSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name Auto Tech Program/Witten Property
HA# FTM
Type of Material Miscellaneous Material
Quantity of Material 231 SF
Material Location
Foyer and restrooms
Material Description
Floor tile mastic

Comments

This material overall was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/27/2011
Current Inspection Date 6/27/2011
Current Assessment Rating NA Not Applicable
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323