

GREATER CLARK COUNTY SCHOOLS

NEW WASHINGTON HIGH SCHOOL/MIDDLE SCHOOL

AHERA

ASBESTOS MANAGEMENT PLAN

**DESIGNATED PERSON
TRUTH AND CORRECT STATEMENT**

Local Education Agency – Greater Clark County Schools
2112 Utica-Sellersburg Road
Jeffersonville, Indiana 47130

Designated Person - Alliance Environmental Group, Inc.
Sandra Shadley
5153 Commerce Square Drive, Suite E
Indianapolis, Indiana 46237

This Truth and Correct Statement, as outlined in 40 CFR 763.93(i), certifies that the general, local education agency responsibilities, as stipulated by 40 CFR 763.84, have been or will be met.

These responsibilities include:

1. Ensure that the activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with 40 CFR 763 Subpart E.
2. Ensure all custodial and maintenance employees are properly trained as required by 40 CFR 763 Subpart E and other applicable Federal and/or State regulations (e.g., the Occupational Safety and Health Administration Asbestos Standard for Construction, the EPA Worker Protection Rule, or applicable State regulations).
3. Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress.
4. Ensure that short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.
5. Ensure that warning labels are posted in accordance with Section 763.95.
6. Ensure management plans are available for inspection and notification of such availability has been provided as specified in the management plan under Section 763.93(g).
7. The undersigned person designated by the LEA pursuant to Section 763.84(g) (1) has received adequate training as stipulated in Section 763.84(g) (2).
8. The LEA has and will consider whether any conflict of interest may arise from the interrelationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under Part 763.

Signature:  Date: November 6, 2016

Sandra S. Shadley

ASBESTOS PROGRAM MASTER INDEX

The following volumes are part of the Asbestos Program for the **GREATER CLARK COUNTY SCHOOLS**:

- A. Original Asbestos Management Plan for each school building.
- B. Asbestos Management Plan Supplement for each school building.
 - 1. Amendments to Management Plan
 - 2. Remaining Materials Report
 - 3. Surveillance, Reinspection and Additional Bulk Sampling Information
 - 4. Annual Notifications, Accreditations and Training Records
 - 5. Operations and Maintenance Records
 - 6. Asbestos Removal Projects
 - 7. Short Term Worker Program

Copies of both volumes are found in the respective buildings. The Administration Building also contains duplicate copies of both volumes for each building in their entirety.

GREATER CLARK COUNTY SCHOOLS
NEW WASHINGTON HIGH SCHOOL
TABLE OF CONTENTS

AMENDMENTS TO MANAGEMENT PLAN	1
REMAINING MATERIALS REPORT	2
SURVEILLANCE, REINSPECTION AND ADDITIONAL BULK SAMPLING INFORMATION	3
ANNUAL NOTIFICATIONS, ACCREDITATIONS, AND TRAINING	4
OPERATIONS AND MAINTENANCE RECORDS	5
ASBESTOS REMOVAL PROJECTS	6
SHORT TERM WORKER INFORMATION	7

AMENDMENTS TO THE MANAGEMENT PLAN

GREATER CLARK COUNTY SCHOOLS
NEW WASHINGTON HIGH SCHOOL

LEA RESPONSIBILITY CERTIFICATION

LEA Designated Person - ALLIANCE INDIANA, INC.



Signature - Bruce Wallace, President/CEO

May 1, 1995

Date

ACCREDITATION STATEMENT

The Greater Clark County Schools ensures that the following items will be carried out:

Activities of any persons who perform inspections, reinspections, and periodic surveillance, develop and update management plans, and develop and implement response actions, including operations and maintenance, are carried out in accordance with Subpart E of this part.

All custodial and maintenance employees are properly trained as required by this Subpart E and other applicable Federal and/or State regulations (e.g., the OSHA asbestos standard for construction, the EPA worker protection rule, or applicable State regulations).

Workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post response action activities, including periodic reinspection and surveillance activities that are planned or in progress.

Short-term workers (e.g., telephone repair workers, utility workers, or exterminators) who may come in contact with asbestos in a school are provided information regarding the locations of ACBM and suspected ACBM assumed to be ACM.

Warning labels are posted in accordance with 763.95.

Management plans are available for inspection and notification of such availability has been provided as specified in the management plan under 763.93(g).

Designate a person to ensure that requirements under this section are properly implemented.

Designated person receives adequate training to perform duties assigned under this section. Such training shall provide, as necessary, basic knowledge of:

Health effects of asbestos

Detection, identification, and assessment of ACM

Options for controlling ACBM

Asbestos management programs

Relevant Federal and State regulations concerning asbestos, including those in this Subpart E and those of the OSHA, U.S. Department of Labor, the U.S. Department of Transportation and the U.S. Environmental Protection Agency.

Consider whether any conflict of interest may arise from the interrelationship among accredited personnel and whether that should influence the selection of accredited personnel to perform activities under this subpart.

AMENDMENT TO THE MANAGEMENT PLAN

LEA Name - Greater Clark County Schools
Building - New Washington High School
Subject - LEA Designated Person Change

Effective May 1, 1995 the Designated Person for the Greater Clark County Schools is:

Alliance Indiana, Inc.
1433 Sadlier Circle West Drive
Indianapolis, Indiana 46239
(317) 351-5600

Management Planner: Rex Gaddis

Accreditation No. 192218025



Signature

May 1, 1995

Date

**AMENDMENT TO THE
AHERA MANAGEMENT PLAN**

Building - New Washington Middle/High School

Subject- New material

Reference - HA A Cove Base

Original Assessment - No assessment in original inspection.


Amended Assessment - The cove base in the building was not addressed in the original inspection. The material is considered to be suspect by EPA. The material will be assumed to contain asbestos and treated as such until a future renovation when it will be sampled.

Management Planner


Rex Gaddis

Indiana Department of Environmental Management Accreditation

192218025



Signature



Date

**AMENDMENT TO THE
AHERA MANAGEMENT PLAN**

Building - New Washington Middle/High School

Subject- New material

Reference - HA B Cove Base Mastic

Original Assessment - No assessment in original inspection.

Amended Assessment - The cove base mastic in the building was not addressed in the original inspection. The material is considered to be suspect by EPA. The material will be assumed to contain asbestos and treated as such until a future renovation when it will be sampled.

Management Planner

Rex Gaddis

Indiana Department of Environmental Management Accreditation

192218025



Signature

9/5/95

Date

AMENDMENT TO MANAGEMENT PLAN


Building Name - New Washington Middle/High School

Subject - Addition of Suspect Material to Management Plan


Amendment - Homogeneous area designation "C" covering ductwork flex connectors overhead in the gymnasium has been added to the Management Plan. This material is suspect for asbestos content. It will be treated as ACM until it is sampled by an accredited inspector and analyzed by an accredited laboratory.

Management Planner: George Wm. Ogle

Accreditation Number: 191928071



Signature



Date

AMENDMENT TO MANAGEMENT PLAN

Building Name - New Washington Middle/High School
Subject - Removal of Material from Management Plan
Amendment - Homogeneous area designation "C" covering ductwork flex connectors will be removed from the Management Plan. This material was removed nonfriable along with the units during the 2008 renovation.

Management Planner: George Wm. Ogle

Accreditation Number: 190903027

Signature

George W Ogle

Date

04 September 2009

AMENDMENT TO MANAGEMENT PLAN

LEA Name - Greater Clark County Schools
Subject - LEA Designated Person Change
Amendment - Effective March 2005, the Designated Person for the Greater Clark County Schools is:

Alliance Environmental Group, Inc.
5340 Commerce Circle, Suite E
Indianapolis, Indiana 46237
(317) 865-3400

Personnel contributing to this Management Plan are licensed in according with 40 CFR 763.93(e)(12).

Management Planner: Sandra S. Shadley

Accreditation Number: 19A002720


Signature



Date


AMENDMENT TO MANAGEMENT PLAN

Building Name - New Washington Middle/High School
Subject - Quantity update to Homogeneous Area A
Amendment - Most of the old brown cove base was removed in a non-friable manner during the 2008 renovation. This material still remains in the fish room/agriculture department by the boiler room.

Management Planner: Sandra Shadley

Accreditation Number: 19A002720


Signature


Date

AMENDMENT TO MANAGEMENT PLAN

Building Name - New Washington Middle/High School
Subject - Addition of Homogeneous Area D
Amendment - Fire doors that were not assessed in the initial inspection. They are suspect material and are being added to the management plan until proper sampling has been completed.

Management Planner: Sandra Shadley

Accreditation Number: 19A002720


Signature


Date

REMAINING MATERIALS

Greater Clark County School Corporation

Remaining Materials Report

4/23/2020

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

1/14/2020

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

5/16/2019

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

11/14/2018

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

5/2/2018

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

10/18/2017

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

4/13/2017

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

11/3/2016

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

4/28/2016

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County School Corporation

Remaining Materials Report

10/20/2015

HA ID	HA Description	Quantity		Asbestos	HA Location	Planned Response Action
<u>New Washington High School/Middle School</u>						
05	Mastic (VAT)	18283	SF	Assumed	Throughout building	O&M
A	Cove base (brownish color)	Unquantified	LF	Assumed	Custodial closets on (1st and 2nd Floor)	O&M
B	Cove Base Mastic	Approx 4600	LF	Assumed	Throughout building	O&M
D	Fire Doors	7	Unit(s)	Assumed	Activity Room and Boiler Room	O&M

Greater Clark County Schools
Remaining Materials Report
April 22, 2015

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
Remaining Materials Report
October 22, 2014**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

Greater Clark County Schools
Remaining Materials Report
April 21, 2014

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
Remaining Materials Report
October 24, 2013**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
 Remaining Materials Report
 April 24, 2013**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
 Remaining Materials Report
 October 24, 2012**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
 Remaining Materials Report
 June 25, 2012**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Custodial closets on (1st and 2nd Floor)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Activity Room and Boiler Room	O & M

**Greater Clark County Schools
Remaining Materials Report
June 27, 2011**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Agriculture Department - (Fish Room)	O & M
				& wet closets on (1st and 2nd Floor)	
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Agriculture Department/Fish Room and Boiler Room	O & M

**Greater Clark County Schools
Remaining Materials Report
December 6, 2010**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Agriculture Department - Fish Room	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Agriculture Department/Fish Room and Boiler Room	O & M

**Greater Clark County Schools
Remaining Materials Report
June 30, 2010**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	Unquantified LF	A	Agriculture Department - Fish Room	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
D	Fire Doors	7 Eac	A	Agriculture Department/Fish Room and Boiler Room	O & M

**Greater Clark County Schools
 Remaining Materials Report
 December 7, 2009**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	QUANTIFIED LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
June 11, 2009

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base (brownish color)	QUANTIFIED LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M

**Greater Clark County Schools
Remaining Materials Report
December 10, 2008**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 200 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	Eac	A	Wrestling storage room	Removed

**Greater Clark County Schools
Remaining Materials Report
June 30, 2008**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	2 Eac	A	Wrestling storage room	O & M

**Greater Clark County Schools
Remaining Materials Report
December 14, 2007**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	6 Eac	A	Overhead in gymnasiums (2 Each) and wrestling storage room	O & M

7

**Greater Clark County Schools
Remaining Materials Report
July 9, 2007**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	6 Eac	A	Overhead in gymnasiums (2 Each) and wrestling storage room	O & M

**Greater Clark County Schools
Remaining Materials Report
December 18, 2006**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	6 Eac	A	Overhead in gymnasiums (2 Each) and wrestling storage room	O & M

**Greater Clark County Schools
 Remaining Materials Report
 June 28, 2006**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	6 Eac	A	Overhead in gymnasiums (2 Each) and wrestling storage room	O & M

**Greater Clark County Schools
Remaining Materials Report
January 25, 2006**

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M
C	Ductwork flex connectors	6 Eac	A	Overhead in gymnasiums (2 Each) and wrestling storage room	O & M

Greater Clark County Schools
 Remaining Materials Report
 July 20, 2005

HA#	Material	Quantity		ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>						
05	Mastic (VAT)	18,283	SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600	LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600	LF	A	Throughout the building	O & M
C	Ductwork flex connectors	2	Each	A	Overhead in gymnasium	O & M

Greater Clark County Schools
 Remaining Materials Report
 December 9, 2004

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M

Greater Clark County Schools
 Remaining Materials Report
 July 2, 2004

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building (except band room, choir room, and auditorium)	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
December 9, 2003

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 4,600 LF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
June 13, 2003

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities	
<u>New Washington Middle\High School</u>						
05	Mastic (VAT)	18,283	SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600	LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 4,600	LF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
December 18, 2003

HA#	Material	Quantity	ACBM	Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>						
05	Mastic (VAT)	18,283 SF		A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF		A	Throughout the building	O & M
B	Cove base mastic	Approx. 4,600 LF		A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
June 19, 2002

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 1,500 SF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
July 12, 2001

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 1,500 SF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
December 12, 2001

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 1,500 SF	A	Throughout the building	O & M

Greater Clark County Schools
Remaining Materials Report
January 11, 2001

HA#	Material	Quantity	ACBM Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>					
05	Mastic (VAT)	18,283 SF	A	Throughout the building	O & M
A	Cove base	Approx. 4,600 LF	A	Throughout the building	O & M
B	Cove base mastic	Approx. 1,500 SF	A	Throughout the building	O & M

**Greater Clark County Schools
 Remaining Materials Report
 June 29, 2000**

HA#	Material	Quantity	ACBM	Y/A	Location	Planned Activities
<u>New Washington MiddleHigh School</u>						
05	Mastic (VAT)	18,283	SF	A	Throughout building	O & M
A	Cove Base	Unquantified	LF	A	Throughout building	O & M
B	Cove Base Mastic	Unquantified	LF	A	Throughout building	O & M

Greater Clark County Schools
Remaining Materials Report
February 23, 2000

HA#	Material	Quantity	ACBM	Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>						
05	Mastic (VAT)	18283	SF	A	Throughout building	O & M
A	Cove Base	Unquantified	LF	A	Throughout building	O & M
B	Cove Base Mastic	Unquantified	LF	A	Throughout building	O & M

Greater Clark County Schools
Remaining Materials Report
July 6, 1999

HA#	Material	Quantity	ACBM	Y/A	Location	Planned Activities
<u>New Washington Middle\High School</u>						
05	Mastic (VAT)	18283	SF	A	Throughout building	O & M
A	Cove Base	Unquantified	LF	A	Throughout building	O & M
B	Cove Base Mastic	Unquantified	LF	A	Throughout building	O & M

*PERIODIC SURVEILLANCE
REINSPECTION
ADDITIONAL BULK SAMPLING
INFORMATION*

ASSESSMENTS FOR AHERA

1. Damaged or significantly damaged thermal systems insulation.
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

If a material is non-friable, it does not require an assessment rating under AHERA.

Due to the differences in what is required of the LEA for damaged material compared to significantly damaged material, Alliance has modified the assessment scale to the following:





- 1A. Significantly damaged thermal systems insulation.
- 1B. Damaged thermal systems insulation.
- 4A. Significantly damaged friable miscellaneous ACM.
- 4B. Damaged friable miscellaneous ACM.

PERIODIC SURVEILLANCES

SURVEILLANCE INFORMATION
PERIODIC SURVEILLANCE PLAN
GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each re-inspection will be maintained in this binder.

DATE PLANNED	DATE COMPLETED	COMPLETED BY
<u>October 2014</u>	October 22, 2014	
<u>April 2015</u>	April 22, 2015	
<u>October 2015</u>	October 20, 2016	
<u>April 2016</u>	RE-INSPECTION	
<u>October 2016</u>	November 3, 2016	
<u>April 2017</u>	April 13, 2017	
<u>October 2017</u>	October 18, 2017	
<u>April 2018</u>	May 2, 2018	
<u>October 2018</u>	November 14, 2018	
<u>April 2019</u>	RE-INSPECTION	
<u>October 2019</u>	January 14, 2020	
<u>April 2020</u>	April 23, 2020	
<u>October 2020</u>		

SURVEILLANCE INFORMATION

PERIODIC SURVEILLANCE PLAN

GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each re-inspection will be maintained in this binder.

<u>April 2021</u>	_____	_____
<u>October 2021</u>	_____	_____
<u>April 2022</u>	RE-INSPECTION	_____
<u>October 2022</u>	_____	_____
<u>April 2023</u>	_____	_____
<u>October 2023</u>	_____	_____
<u>April 2024</u>	_____	_____
<u>October 2024</u>	_____	_____
<u>April 2025</u>	RE-INSPECTION	_____
<u>October 2025</u>	_____	_____
<u>April 2026</u>	_____	_____
<u>October 2026</u>	_____	_____

SURVEILLANCE INFORMATION

PERIODIC SURVEILLANCE PLAN SCHEDULE

GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each re-inspection will be maintained in this binder.

<u>DATE PLANNED</u>	<u>DATE COMPLETED</u>	<u>COMPLETED BY</u>
<u>JUNE 2009</u>	<u>June 2009</u>	<u>Bill Ogle</u>
<u>DECEMBER 2009</u>	<u>Dec 2009</u>	<u>Bill Ogle</u>
<u>JUNE 2010</u>	<u>Reinspection</u>	<u>Sandy Shadley</u>
<u>DECEMBER 2010</u>	<u>December 2010</u>	<u>Paul Knick</u>
<u>JUNE 2011</u>	<u>June 2011</u>	<u>Sandy Shadley</u>
<u>DECEMBER 2011</u>	<u>_____</u>	<u>_____</u>
<u>JUNE 2012</u>	<u>June 2012</u>	<u>Jeff Hechtin</u>
<u>DECEMBER 2012</u>	<u>October 2012</u>	<u>Jeff Hechtin</u>
<u>JUNE 2013</u>	<u>Reinspection</u>	<u>Jeff Hechtin</u>
<u>DECEMBER 2013</u>	<u>_____</u>	<u>_____</u>

PERIODIC SURVEILLANCE PLAN

GREATER CLARK COUNTY SCHOOLS

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long as the material remain in the building, as required by the Asbestos Hazard Emergency Response Act (AHERA). This periodic surveillance shall be conducted on a semi-annual basis as required by law.

Records of each reinspection will be maintained in this binder.

<u>DATE PLANNED</u>	<u>DATE COMPLETED</u>	<u>COMPLETED BY</u>
<u>JUNE 2003</u>	<u>June '03</u>	<u>C. Sparks</u>
<u>DECEMBER 2003</u>	<u>Dec '03</u>	<u>C. Sparks</u>
<u>JUNE 2004</u>	<u>REINSPECTION</u>	<u>C. Sparks</u>
<u>DECEMBER 2004</u>	<u>Dec '04</u>	<u>C. Sparks</u>
<u>JUNE 2005</u>	<u>July '05</u>	<u>J. Ogle</u>
<u>DECEMBER 2005</u>	<u>Jan 06</u>	<u>Boyer</u>
<u>JUNE 2006</u>	<u>June 06</u>	<u>C. Ams</u>
<u>DECEMBER 2006</u>	<u>Dec 06</u>	<u>Doye</u>
<u>JUNE 2007</u>	<u>REINSPECTION</u>	
<u>DECEMBER 2007</u>	<u>December 2007</u>	<u>Bill Ogle</u>
<u>JUNE 2008</u>	<u>June 2008</u>	<u>Bill Ogle</u>
<u>DECEMBER 2008</u>	<u>December 2008</u>	<u>Bill Ogle</u>

PERIODIC SURVEILLANCE PLAN

GREATER CLARK COUNTY SCHOOLS

NEW WASHINGTON HIGH SCHOOL

The ACBM in this building will be periodically inspected to determine any change in the condition of the materials for as long they remain in the building. This inspection will be conducted semi-annually.

The following table outlines the dates on which these inspections should take place in this school building.

PERIODIC SURVEILLANCE SCHEDULE

<u>DATE PLANNED</u>	<u>DATE COMPLETED</u>	<u>COMPLETED BY</u>
<u>DECEMBER 1995</u>	<u>12-95</u>	<u>Alliance</u>
<u>JUNE 1996</u>	<u>6-96</u>	<u>Alliance</u>
<u>DECEMBER 1996</u>	<u>12-96</u>	<u>Alliance</u>
<u>JUNE 1997</u>	<u>7-97</u>	<u>Alliance</u>
<u>DECEMBER 1997</u>	<u>1-98</u>	<u>Alliance</u>
<u>JUNE 1998</u>	<u>REINSPECTION</u>	<u>Alliance</u>
<u>DECEMBER 1998</u>	<u>12-98</u>	<u>Alliance</u>
<u>JUNE 1999</u>	<u>June '99</u>	<u>Alliance</u>
<u>DECEMBER 1999</u>	<u>Dec. '99</u>	<u>Alliance</u>
<u>JUNE 2000</u>	<u>June 2000</u>	<u>Alliance</u>
<u>DECEMBER 2000</u>	<u>Jan. '01</u>	<u>Pat Wilson</u>
<u>JUNE 2001</u>	<u>REINSPECTION</u>	<u>P. Wilson</u>
<u>DECEMBER 2001</u>	<u>Dec '01</u>	<u>A. Kimbrough</u>
<u>JUNE 2002</u>	<u>June '02</u>	<u>R. Calvert</u>
<u>DECEMBER 2002</u>	<u>Dec '02</u>	<u>C. Sparks</u>

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 4/23/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 1/14/2020

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Michael J. Ardis

State IN

Accreditation Number 19A007304

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 11/14/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 11/14/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 11/14/2018


Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None
Planned Response Action	O&M		

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 11/14/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 5/2/2018

Material Assessment


Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact	Vibration	Air
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector 
Benjamin S. Hood

State IN
Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF
Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.
Asbestos Assumed
Friable No
Original Inspection 5/31/1995
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 5/2/2018

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M



Inspector _____
Dustin Hawkins

State IN
Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF
Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.
Asbestos Assumed
Friable No
Original Inspection 5/31/1995
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector _____
Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 10/18/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF
Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.
Asbestos Assumed
Friable No
Original Inspection 5/31/1995
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector _____
Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector _____
Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 4/13/2017

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Jamie Hosier

State Indiana

Accreditation Number 19A007179

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF
Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.
Asbestos Assumed
Friable No
Original Inspection 5/31/1995
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF
Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.
Asbestos Assumed
Friable No
Original Inspection 5/31/1995
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 11/3/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M



Inspector

Dustin Hawkins

State IN

Accreditation Number 19A007194

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Periodic Surveillance

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 10/20/2015

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector




Benjamin S. Hood

State IN

Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 4/22/2015
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 4/22/2015
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 4/22/2015
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each


Material Location
Activity Room and Boiler Room

Material Description
Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 4/22/2015
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039


PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 10/22/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/22/2014
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location

Throughout the building


Material Description

Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/22/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each


Material Location
Activity Room and Boiler Room

Material Description
Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 10/22/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M



Inspector

Benjamin S. Hood

State Indiana
Accreditation Number 19A001039

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 4/21/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 4/21/2014
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 4/21/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each
Material Location
Activity Room and Boiler Room

Material Description

Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 4/21/2014
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 10/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State

Indiana

Accreditation Number

19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments

Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building


Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location
Activity Room and Boiler Room

Material Description

Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 10/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF


Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 10/24/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/24/2012
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 10/24/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location
Activity Room and Boiler Room

Material Description

Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 10/24/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF


Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 6/25/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Jeffery P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments

Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/25/2012
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Jeffrey P. Rechin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/25/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rechin

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location
Activity Room and Boiler Room


Material Description
Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 6/25/2012
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffery P. Rechten

State Indiana
Accreditation Number 19A003594

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 6/27/2011
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location
Agriculture Department - (Fish Room) & wet closets on (1st and 2nd Floor)

Material Description

Cove base (brownish color)

Comments

Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was found in the fish room in the agriculture department by the boiler room and in the custodial closets.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/27/2011
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. No cove base mastic was visible to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/27/2011
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location
Agriculture Department/Fish Room and Boiler Room

Material Description
Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 6/27/2011
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/6/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Paul W. Krick

State Indiana
Accreditation Number 197812124

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Agriculture Department - Fish Room

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was found in the fish room in the agriculture department by the boiler room during this June 2010 Third Year Inspection.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/6/2010
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Paul W. Krick

State Indiana
Accreditation Number 197812124

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. No cove base mastic was visible to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/6/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Paul W. Krick

State Indiana
Accreditation Number 197812124

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location

Agriculture Department/Fish Room and Boiler Room

Material Description

Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Surveillance Date 12/6/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Paul W. Krick

State Indiana
Accreditation Number 197812124

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/3/2009
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle/High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material UNQUANTIFIED LF
Material Location

Throughout the building

Material Description

Cove base (brownish color)

Comments

No brown cove base was located. The head custodian was sure that the last had been removed during the summer. Further investigation is needed to verify this.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/3/2009
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. No cove base mastic was visible to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/3/2009
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 6/11/2009
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector _____

George William Ogle

State IN
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material UNQUANTIFIED LF

Material Location
Throughout the building


Material Description
Cove base (brownish color)

Comments

The cafeteria area cove base was removed non-friable during the Christmas break. The remaining material throughout the building was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/11/2009
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State IN
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. No cove base mastic was visible to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 6/11/2009
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State IN
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/10/2008
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 200 LF
Material Location
Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

All cove base except the cafeteria area has been removed non-friable during the renovation (cafeteria area is scheduled to be done during Christmas break). The remaining material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/10/2008
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF


Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was exposed in many areas where new cove base has not yet been installed. It was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/10/2008
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 0 Each


Material Location
Wrestling storage room

Material Description
Ductwork flex connectors

Comments
The two in the wrestling storage room were removed non-friable along with the units during the renovation. This homogeneous area will be removed from the Management Plan.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 7/19/2005
Current Surveillance Date 12/10/2008
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage XX
Removed Yes
Planned Response Action Removed

Inspector



George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/6/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

This material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/6/2007
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington MiddleHigh School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/6/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 6 Each
Material Location
Overhead in gymnasiums (2 Each) and wrestling storage room

Material Description
Ductwork flex connectors

Comments

The material is not in poor condition. The two in the wrestling storage room are a black vinyl type, while the four in the gymnasium are so high it's not possible to tell what type of material they are.

Does Material Contain Asbestos?	Assumed	
Is it Friable?	No	
Original Inspection Date	7/19/2005	
Current Surveillance Date	12/6/2007	
Current Assessment Rating	NR	Not Required
Cause of Damage	No Damage	
Accessible	Yes	
Potential for Damage	Low	
Removed	No	
Planned Response Action	O & M	

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington MiddleHigh School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Reinspection Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

This material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was not exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 6 Each

Material Location
Overhead in gymnasiums (2 Each) and wrestling storage room

Material Description
Ductwork flex connectors

Comments
The material is not in poor condition. The two in the wrestling storage room are a black vinyl type, while the four in the gymnasium are so high it's not possible to tell what type of material they are.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 7/19/2005
Current Reinspection Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/19/2006
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location

Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

This material was not in poor condition.

Does Material Contain Asbestos?	Assumed
Is it Friable?	No
Original Inspection Date	5/31/1995
Current Surveillance Date	12/19/2006
Current Assessment Rating	NR Not Required
Cause of Damage	Deterioration & Age
Accessible	Yes
Potential for Damage	Low
Removed	No
Planned Response Action	O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location

Throughout the building

Material Description

Cove base mastic

Comments

This material was not exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/19/2006
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 6 Each

Material Location

Overhead in gymnasiums (2 Each) and wrestling storage room

Material Description

Ductwork flex connectors

Comments

The material is not in poor condition. The two in the wrestling storage room are a black vinyl type, while the four in the gymnasium are so high it's not possible to tell what type of material they are.

Does Material Contain Asbestos?	Assumed	
Is it Friable?	No	
Original Inspection Date	7/19/2005	
Current Surveillance Date	12/19/2006	
Current Assessment Rating	NR	Not Required
Cause of Damage	No Damage	
Accessible	Yes	
Potential for Damage	Low	
Removed	No	
Planned Response Action	O & M	

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 1/24/2006
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

This material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 1/24/2006
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was not exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 1/24/2006
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 6 Each

Material Location

Overhead in gymnasiums (2 Each) and wrestling storage room

Material Description

Ductwork flex connectors

Comments


The material is not in poor condition. The two in the wrestling storage room are a black vinyl type, while the four in the gymnasium are so high it's not possible to tell what type of material they are.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 7/19/2005
Current Surveillance Date 1/24/2006
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



George William Ogle

State Indiana
Accreditation Number 191523030




PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
Other than gaps between tiles, no mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 7/19/2005
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector _____

George William Ogle

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building (except band room, choir room, and auditorium)
Material Description
Cove base
Comments
This material was not in poor condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 7/19/2005
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M
Inspector _____

George William Ogle
State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 7/19/2005
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 2 Each

Material Location
Overhead in gymnasium


Material Description
Ductwork flex connectors

Comments


One sample of the material in the wrestling room was analyzed 7/12/1989. It was found to be negative for asbestos content. However, more samples are necessary to call all this material negative. This material is suspect for asbestos content. It will be treated as ACM until it is properly sampled and analyzed. The material is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 7/19/2005
Current Surveillance Date 7/19/2005
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 this material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 12/8/2004
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building (except band room, choir room, and auditorium)
Material Description
Cove base

Comments

This material was removed non-friable from the band room, choir room, and auditorium during a small renovation project in 2004. The new replacement material is not suspect for asbestos content. The remaining original material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/8/2004
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF


Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was not in poor condition where exposed.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 12/8/2004
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF


Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 this material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 12/08/2003
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base

Comments

This material was not in poor condition overall. All cove base has been removed in the band room. Material shows minor signs of wear and there are several pieces missing throughout the building.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/08/2003
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
This material was not in poor condition where exposed.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/08/2003
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 the mastic is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 06/13/2003
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base

Comments

Material is not in poor condition overall. All cove base has been removed in the band room. Material shows minor signs of wear and there are several pieces missing throughout the building.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/13/2003
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not in poor condition where exposed.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/13/2003
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M
Inspector


Christian Sparks
State Indiana
Accreditation Number 190804103



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 the mastic is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 12/18/2002
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base

Comments

Material is not in poor condition overall. All cove base has been removed in the band room. Material shows minor signs of wear and there are several pieces missing throughout the building.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/18/2002
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M


Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not in poor condition where exposed.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/18/2002
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M
Inspector


Christiaan Sparks
State Indiana
Accreditation Number 190804103



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 the mastic is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 06/18/2002
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Richard D. Calvert

State Indiana
Accreditation Number 315989970

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base

Comments

Material is not in poor condition. There is one corner piece missing at the top of the stairs next to the office. All cove base has been removed in the band room. Material shows minor signs of wear throughout. There is also a piece missing by the main entrance.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/18/2002
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Richard D. Calvert

State Indiana
Accreditation Number 315989970

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 1,500 SF

Material Location
Throughout the building

Material Description
Cove base mastic


Comments
Where exposed at the top of the stairs and by the main entrance, the material is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/18/2002
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Richard D. Calvert

State Indiana
Accreditation Number 315989970



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building


Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, the restroom and in rooms 107 and 209 the mastic is not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 12/11/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Stephen Kimbrough

State Indiana
Accreditation Number 191914122

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base

Comments

Material is not in poor condition. There is one corner piece missing at the top of the stairs next to the office. All cove base has been removed in the band room. Material shows minor signs of wear throughout. There is also a piece missing by the main entrance.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/11/2001
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Stephen Kimbrough

State Indiana
Accreditation Number 191914122

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 1,500 SF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
Where exposed at the top of the stairs and by the main entrance, the material is not in poor condition.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/11/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Stephen Kimbrough

State Indiana
Accreditation Number 191914122



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
Where exposed on the main gymnasium balcony, the restroom and in rooms 107 and 209 the mastic is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 01/11/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building


Material Description
Cove base

Comments

Material is in good condition. There is one corner piece missing at the top of the stairs next to the office. All cove base has been removed in the main portion of the band room. Material shows minor signs of wear throughout.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 01/11/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 1,500 SF


Material Location
Throughout the building

Material Description
Cove base mastic

Comments
Where exposed at the top of the stairs, the material is in good condition.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 01/11/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout building

Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, the restroom and in rooms 107 and 209 the mastic is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 06/29/2000
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogden

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Throughout building


Material Description
Cove Base

Comments

Material is in good condition. There are two pieces missing at the top of the stairs by the pool and one corner piece missing at the top of the stairs next to the office. All cove base has been removed in the main portion of the band room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/29/2000
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF


Material Location
Throughout building

Material Description
Cove Base Mastic


Comments
Where exposed at the top of the stairs by the pool and in the band room, the material is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/29/2000
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191523030



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18283 SF
Material Location
Throughout building
Material Description
Mastic (VAT)
Comments
Material is not exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 12/08/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Matthew Wallace

State Indiana
Accreditation Number 191219020

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Throughout building


Material Description
Cove Base

Comments

Material is in good condition. There are two pieces missing at the top of the stairs by the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/08/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Matthew Wallace

State Indiana
Accreditation Number 191219020

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Throughout building


Material Description
Cove Base Mastic

Comments

Where exposed at the top of the stairs by the pool, material is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/08/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Matthew Wallace

State Indiana
Accreditation Number 191219020



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18283 SF

Material Location
Throughout building

Material Description
Mastic (VAT)

Comments
A small amount of this material is exposed on the stairs near the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 06/24/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Matthew Wallace

State Indiana
Accreditation Number 191219020

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location
Throughout building
Material Description
Cove Base
Comments
Material is in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/24/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector _____

Matthew Wallace

State Indiana
Accreditation Number 191219020

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location
Throughout building
Material Description
Cove Base Mastic
Comments
Material is assumed to be in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 06/24/1999
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector _____

Matthew Wallace

State Indiana
Accreditation Number 191219020



PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington MiddleHigh School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18283 SF
Material Location
Throughout building
Material Description
Mastic (VAT)

Comments

A small amount of this material is exposed on the stairs near the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Surveillance Date 12/29/1998
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector




Clint Yates

State Indiana
Accreditation Number 193804035

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location
Throughout building
Material Description
Cove Base
Comments
Material is in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/29/1998
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector




Clint Yates

State Indiana
Accreditation Number 193804035

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location
Throughout building
Material Description
Cove Base Mastic
Comments
Material is assumed to be in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Surveillance Date 12/29/1998
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Clint Yates

State Indiana
Accreditation Number 193804035



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location Throughout building
Material Description Mastic (VAT)

Comments

A small amount of this material is exposed on the stairs near the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/ 1/92
Current Surveillance Date 1/15/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Karen Foxx

State Indiana
Accreditation Number 191129014

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location
Throughout building
Material Description
Cove Base
Comments
Material is in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 1/15/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Karen Foxx

State Indiana
Accreditation Number 191129014

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location Throughout building
Material Description Cove Base Mastic
Comments Material is assumed to be in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 1/15/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Karen Foxx

State Indiana
Accreditation Number 191129014



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout building

Material Description
Mastic (VAT)

Comments

A small amount of this material is exposed on the stairs near the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/ 1/92
Current Surveillance Date 7/ 1/97
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector




Karen Foxx

State Indiana
Accreditation Number 191129014

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location Throughout building
Material Description Cove Base
Comments Material is in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 7/ 1/97
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Karen Foxx

State Indiana
Accreditation Number 191129014

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location
Throughout building
Material Description
Cove Base Mastic
Comments
Material is assumed to be in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 7/ 1/97
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Karen Foxx

State Indiana
Accreditation Number 191129014



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout building


Material Description
Mastic (VAT)

Comments

This material is assumed to be asbestos containing. A small amount is exposed on the stairs near the pool. No change.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/ 1/92
Current Surveillance Date 12/16/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Clint Yates

State

Indiana

Accreditation Number

193804035

PERIODIC SURVEILLANCE REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location
Throughout building
Material Description
Cove Base

Comments

Material is assumed to be positive and will be treated as ACM until it is sampled. It is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 12/16/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Clint Yates

State Indiana
Accreditation Number 193804035

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material LF

Material Location
Throughout building


Material Description
Cove Base Mastic

Comments

Material is assumed to be positive and will be treated as ACM until it is sampled.
Material is in good condition.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 12/16/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Clint Yates

State Indiana
Accreditation Number 193804035



PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout building


Material Description
Mastic (VAT)

Comments

This material is assumed to be asbestos containing. A small amount is exposed on the stairs near the pool. No change.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/ 1/92
Current Surveillance Date 6/21/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Rex Gaddis

State Indiana
Accreditation Number 190908032

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location
Throughout building
Material Description
Cove Base

Comments

Material is assumed to be positive and will be treated as ACM until it is sampled. It is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 6/21/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Rex Gaddis

State Indiana
Accreditation Number 190908032

PERIODIC SURVEILLANCE REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material LF

Material Location
Throughout building


Material Description
Cove Base Mastic

Comments

Material is assumed to be positive and will be treated as ACM until it is sampled.
Material is in good condition.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Surveillance Date 6/21/96
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Rex Gaddis

State Indiana
Accreditation Number 190908032



PERIODIC SURVEILLANCE REPORT

LEA NAME: Greater Clark County Schools
BUILDING NAME: New Washington Middle\High School
HA#: 05
TYPE OF MATERIAL: Miscellaneous Material
QUANTITY OF MATERIAL: 18,283SF
MATERIAL LOCATION:

Throughout Building

MATERIAL DESCRIPTION:


Mastic (VAT)

COMMENTS:

This material is assumed to be asbestos containing. A small amount is exposed on the stairs near the pool.

IS MATERIAL FRIABLE? NO
ORIGINAL INSPECTION DATE: 06/01/92
CURRENT SURVEILLANCE DATE: 12/07/95
CURRENT ASSESSMENT RATING: NR Not Required
CAUSE OF DAMAGE: No Damage
ACCESSIBLE: NO
POTENTIAL FOR DAMAGE: Low
REMOVED: NO
STATE: Indiana

INSPECTOR NAME:


Clint Yates

PERIODIC SURVEILLANCE REPORT

LEA NAME: Greater Clark County Schools
BUILDING NAME: New Washington Middle\High School
HA#: A
TYPE OF MATERIAL: Miscellaneous Material
QUANTITY OF MATERIAL:
MATERIAL LOCATION:

Throughout Building

MATERIAL DESCRIPTION:

Cove Base

COMMENTS:

This material was not addressed in the original inspection. It is assumed to be positive and will be treated as ACM until it is sampled. Material is loose throughout the building, however, it is in good condition, is non-friable and does not need an assessment rating at this time.

IS MATERIAL FRIABLE? NO
ORIGINAL INSPECTION DATE:
CURRENT SURVEILLANCE DATE: 12/07/95
CURRENT ASSESSMENT RATING: NR Not Required
CAUSE OF DAMAGE: No Damage
ACCESSIBLE: YES
POTENTIAL FOR DAMAGE: Low
REMOVED: NO
STATE: Indiana

INSPECTOR NAME:


Clint Yates

PERIODIC SURVEILLANCE REPORT

LEA NAME: Greater Clark County Schools
BUILDING NAME: New Washington Middle\High School
HA#: B
TYPE OF MATERIAL: Miscellaneous Material
QUANTITY OF MATERIAL:
MATERIAL LOCATION:

Throughout Building

MATERIAL DESCRIPTION:

Cove Base Mastic

COMMENTS:

This material was not addressed in the original inspection. It is assumed to be positive and will be treated as ACM until it is sampled. Material is in good condition and is non-friable and does not need an assessment rating at this time.

IS MATERIAL FRIABLE? NO
ORIGINAL INSPECTION DATE:
CURRENT SURVEILLANCE DATE: 12/07/95
CURRENT ASSESSMENT RATING: NR Not Required
CAUSE OF DAMAGE: No Damage
ACCESSIBLE: NO
POTENTIAL FOR DAMAGE: Low
REMOVED: NO
STATE: Indiana

INSPECTOR NAME:


Clint Yates

THIRD YEAR REINSPECTIONS

REINSPECTION PLAN

GREATER CLARK COUNTY SCHOOLS

Reinspection by an accredited building inspector will be scheduled to be performed not more than three years from the date of the original inspection. The reinspection report will then be made a permanent part of this Management Plan. Reinspections will be performed every three years for as long as the building contains ACBM, and will be reinspected once within three years from the date that all ACBM has been removed.

Records of each reinspection should be maintained in this binder.

<u>DATE PLANNED</u>	<u>DATE COMPLETED</u>	<u>COMPLETED BY</u>
<u>JUNE 2007</u>	July 2007	Bill Cole
<u>JUNE 2010</u>	June 2010	Sandy Shadley
<u>JUNE 2013</u>	April 2013	Jeff Hechtin
<u>JUNE 2016</u>	April 2016	Benjamin [Signature]
<u>JUNE 2019</u>	May 2019	[Signature]
<u>JUNE 2022</u>		
<u>JUNE 2025</u>		

REINSPECTION PLAN

GREATER CLARK COUNTY SCHOOLS

NEW WASHINGTON HIGH SCHOOL

The ACBM in this building shall be reinspected every three years to determine any change in the condition of the materials for as long they remain in the building. This reinspection will be conducted tri-annually by an accredited inspector.

The following table outlines the dates on which these inspections should take place in this school building.

REINSPECTION SCHEDULE

<u>DATE PLANNED</u>	<u>DATE COMPLETED</u>	<u>COMPLETED BY</u>
<u>JUNE 1992</u>	<u>JUNE 1992</u>	<u>ASBESTECH</u>
<u>JUNE 1995</u>	<u>June '95</u>	<u>Alliance</u>
<u>JUNE 1998</u>	<u>June '98</u>	<u>Alliance</u>
<u>JUNE 2001</u>	<u>July '01</u>	<u>G. Wilson</u>
<u>JUNE 2004</u>	<u>July '04</u>	<u>C. Sparks</u>

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 5/16/2019

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged	%	Good Condition	
Physical Contact		Vibration	Air
Low/None		Low/None	Low/None

Planned Response Action O&M

Inspector



Sean Stults

State IN

Accreditation Number 19A007184

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID 05
HA Description Mastic (VAT)
HA Type Miscellaneous Material
HA Location Throughout building

Quantity 18283 SF
Comments No mastic was exposed to inspect.
Asbestos Assumed
Friable No

Original Inspection 6/1/1992
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration

Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID A
HA Description Cove base (brownish color)
HA Type Miscellaneous Material
HA Location Custodial closets on (1st and 2nd Floor)

Quantity Unquantified LF

Comments Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Asbestos Assumed

Friable No

Original Inspection 5/31/1995
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

Physical Contact

Low/None

Vibration


Low/None

Air

Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID B
HA Description Cove Base Mastic
HA Type Miscellaneous Material
HA Location Throughout building

Quantity Approx 4600 LF

Comments This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Asbestos Assumed
Friable No

Original Inspection 5/31/1995
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage

Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039

Triennial Reinspection

LEA Name Greater Clark County School Corporation
Building Name New Washington High School/Middle School
Building Number 07
HA ID D
HA Description Fire Doors
HA Type Miscellaneous Material
HA Location Activity Room and Boiler Room

Quantity 7 Unit(s)
Comments Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.
Asbestos Assumed
Friable No
Original Inspection 6/30/2010
Current Inspection 4/27/2016

Material Assessment

Assessment Rating 5 ACBM with potential for damage


Damage Assessment and Potential for Damage

Percent Damaged % Good Condition

<u>Physical Contact</u>	<u>Vibration</u>	<u>Air</u>
Low/None	Low/None	Low/None

Planned Response Action O&M

Inspector



Benjamin S. Hood

State IN

Accreditation Number 19A001039



THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Reinspection Date 4/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF

Material Location
Custodial closets on (1st and 2nd Floor)

Material Description
Cove base (brownish color)

Comments
Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was removed in the fish room in the agriculture department by the boiler room in December 2011. This room is now an activity room.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 4/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. The visible cove base mastic in the activity room was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 4/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location
Activity Room and Boiler Room

Material Description
Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Reinspection Date 4/24/2013
Current Assessment Rating NR Not Rated
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Jeffrey P. Rehtin

State Indiana
Accreditation Number 19A003594

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
No mastic was exposed to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Reinspection Date 6/30/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State IN
Accreditation Number 19A002323

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Unquantified LF
Material Location

Agriculture Department - Fish Room

Material Description

Cove base (brownish color)

Comments

Most of this material was removed in the 2008 renovation in a non-friable manner. Old cove base was found in the fish room in the agriculture department by the boiler room during this third year reinspection.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 6/30/2010
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State

IN

Accreditation Number

19A002323

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments

This material was not documented as being totally removed and is assumed to remain in place behind the new cove base. No cove base mastic was visible to inspect.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 6/30/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State IN
Accreditation Number 19A002323

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# D
Type of Material Miscellaneous Material
Quantity of Material 7 Each

Material Location

Agriculture Department/Fish Room and Boiler Room

Material Description


Fire Doors

Comments

Fire doors were not assessed in the original inspection. The core material is suspect material and is being added to the Management Plan until proper sampling has been completed.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/30/2020
Current Reinspection Date 6/30/2010
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Sandra Shadley

State Indiana
Accreditation Number 19A002323

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location Throughout the building (except band room, choir room, and auditorium)

Material Description

Cove base

Comments

This material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF
Material Location
Throughout the building
Material Description
Mastic (VAT)
Comments
No mastic was exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Surveillance Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not exposed to inspect.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Surveillance Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State

Indiana

Accreditation Number

191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# C
Type of Material Miscellaneous Material
Quantity of Material 6 Each
Material Location
Overhead in gymnasiums (2 Each) and wrestling storage room

Material Description

Ductwork flex connectors

Comments

The material is not in poor condition. The two in the wrestling storage room are a black vinyl type, while the four in the gymnasium are so high it's not possible to tell what type of material they are.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 7/19/2005
Current Surveillance Date 7/11/2007
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


George William Ogle

State Indiana
Accreditation Number 191003027

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building


Material Description
Mastic (VAT)

Comments

Where exposed on the main gymnasium balcony, by the safety shower, the restroom and in rooms 107 and 209 this material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/1/1992
Current Reinspection Date 6/28/2004
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building (except band room, choir room, and auditorium)

Material Description
Cove base

Comments
This material was removed non-friable from the band room, choir room, and auditorium during a small renovation project in 2004. The new replacement material is not suspect for asbestos content. The remaining original material was not in poor condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 6/28/2004
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christian Sparks

State Indiana
Accreditation Number 190804103

THIRD YEAR REINSPECTION REPORT


LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF
Material Location
Throughout the building
Material Description
Cove base mastic
Comments
This material was not in poor condition where exposed.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/1995
Current Reinspection Date 6/28/2004
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Christiaan Sparks

State Indiana
Accreditation Number 190804103



THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout the building

Material Description
Mastic (VAT)

Comments
Where exposed on the main gymnasium balcony, the restroom and in rooms 107 and 209 the mastic is in good condition.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 06/01/1992
Current Reinspection Date 07/12/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material Approx. 4,600 LF

Material Location
Throughout the building


Material Description
Cove base

Comments

Material is in good condition. There is one corner piece missing at the top of the stairs next to the office. All cove base has been removed in the main portion of the band room. Material shows minor signs of wear throughout. There is a piece missing by the main entrance.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Reinspection Date 07/12/2001
Current Assessment Rating NR Not Required
Cause of Damage Deterioration & Age
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material Approx. 1,500 SF

Material Location
Throughout the building

Material Description
Cove base mastic

Comments
Where exposed at the top of the stairs and by the main entrance, the material is in good condition.


Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 05/31/1995
Current Reinspection Date 07/12/2001
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Patrick E. Wilson

State Indiana
Accreditation Number 190824065



THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# 05
Type of Material Miscellaneous Material
Quantity of Material 18,283 SF

Material Location
Throughout building


Material Description
Mastic (VAT)

Comments

A small amount of this material is exposed on the stairs near the pool.

Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 6/ 1/92
Current Reinspection Date 6/ 1/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector



Clint Yates

State Indiana
Accreditation Number 193804035

THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# A
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location
Throughout building
Material Description
Cove Base
Comments
Material is in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Reinspection Date 6/ 1/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible Yes
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Clint Yates

State Indiana
Accreditation Number 193804035


THIRD YEAR REINSPECTION REPORT

LEA Name Greater Clark County Schools
Building Name New Washington Middle\High School
HA# B
Type of Material Miscellaneous Material
Quantity of Material LF
Material Location Throughout building
Material Description Cove Base Mastic
Comments Material is assumed to be in good condition.
Does Material Contain Asbestos? Assumed
Is it Friable? No
Original Inspection Date 5/31/95
Current Reinspection Date 6/ 1/98
Current Assessment Rating NR Not Required
Cause of Damage No Damage
Accessible No
Potential for Damage Low
Removed No
Planned Response Action O & M

Inspector


Clint Yates

State Indiana
Accreditation Number 193804035



THIRD YEAR REINSPECTION REPORT

LEA NAME: Greater Clark County School Corp.
BUILDING NAME: New Washington Middle\High School
HA#: 05
TYPE OF MATERIAL: Miscellaneous Material
QUANTITY OF MATERIAL: 18,283SF
MATERIAL LOCATION:

Throughout Building

MATERIAL DESCRIPTION:

Mastic (VAT)

COMMENTS:

This material is assumed to be asbestos containing. A small amount is exposed on the stairs near the pool.

IS MATERIAL FRIABLE? NO
ORIGINAL INSPECTION DATE: 06/01/92
CURRENT REINSPECTION DATE: 06/28/95
CURRENT ASSESSMENT RATING: NR Not Required
CAUSE OF DAMAGE: No Damage
ACCESSIBLE: NO
POTENTIAL FOR DAMAGE: Low
REMOVED: NO
CURRENT VIDEO TAPE: /
(TAPE NO/FOOTAGE)

INSPECTOR NAME:



Rex Gaddis

STATE: Indiana

ACCREDITATION NO.: 190908032

THIRD YEAR REINSPECTION REPORT

LEA NAME: Greater Clark County School Corp.
BUILDING NAME: New Washington Middle\High School
HA#: A
TYPE OF MATERIAL: Miscellaneous Material
QUANTITY OF MATERIAL:
MATERIAL LOCATION:


Throughout Building

MATERIAL DESCRIPTION:

Cove Base

COMMENTS:

This material was not addressed in the original inspection. It is assumed to be positive and will be treated as ACM until it is sampled. Material is in good condition and is non-friable and does not need an assessment rating at this time.

IS MATERIAL FRIABLE? NO
ORIGINAL INSPECTION DATE:
CURRENT REINSPECTION DATE: 06/28/95
CURRENT ASSESSMENT RATING: NR Not Required
CAUSE OF DAMAGE: No Damage
ACCESSIBLE: NO
POTENTIAL FOR DAMAGE: Low
REMOVED: NO
CURRENT VIDEO TAPE:
(TAPE NO/FOOTAGE) /
INSPECTOR NAME: 
Rex Gaddis
STATE: Indiana
ACCREDITATION NO.: 190908032

THIRD YEAR REINSPECTION REPORT

LEA NAME: Greater Clark County School Corp.

BUILDING NAME: New Washington Middle\High School

HA#: B

TYPE OF MATERIAL: Miscellaneous Material

QUANTITY OF MATERIAL:

MATERIAL LOCATION:

Throughout Building

MATERIAL DESCRIPTION:

Cove Base Mastic

COMMENTS:

This material was not addressed in the original inspection. It is assumed to be positive and will be treated as ACM until it is sampled. Material is in good condition and is non-friable and does not need an assessment rating at this time.

IS MATERIAL FRIABLE? NO

ORIGINAL INSPECTION DATE:

CURRENT REINSPECTION DATE: 06/28/95

CURRENT ASSESSMENT RATING: NR Not Required

CAUSE OF DAMAGE: No Damage

ACCESSIBLE: NO

POTENTIAL FOR DAMAGE: Low

REMOVED: NO

CURRENT VIDEO TAPE: /
(TAPE NO/FOOTAGE)

INSPECTOR NAME:



Rex Gaddis

STATE: Indiana

ACCREDITATION NO.: 190908032

ADDITIONAL BULK SAMPLES

Pace Analytical

Pace Analytical Services, Inc.
5156 East 65th Street
Indianapolis, IN 46220

Tel: 317-845-7730
Fax: 317-845-0630

June 7, 1998

Alliance Indiana, Inc.

Attention: Karen Foxx
1433 Sadlier Circle, West Dr.
Indianapolis, IN 46239

RE: 11 PLM Analyses

Client Project Name:	New Wahington H.S. - Ag Building
Client Project Number:	NGR-07A01
Results Faxed to:	Karen Foxx
Date:	June 5, 1998
Time:	10:57 am
Laboratory Batch Number:	980927
Pace Project Number:	70424.9701


Dear Ms. Foxx:

Enclosed are the results from the bulk asbestos analyses for the 11 samples submitted to the Pace Asbestos Laboratory on June 4, 1998. Percentages were determined by visually estimating the area percentage for each type of fibrous material. Samples estimated to contain less than ten percent asbestos fibers may require quantification by point counting. These samples may be resubmitted at your discretion.

Pace will hold your samples for thirty days after the completion of the analysis. At the end of the thirty day period, it will be our policy to dispose of the samples unless prior arrangements are made.

It has been a pleasure serving you. If there are any questions, please contact me at (317) 849-4990.

Respectfully submitted,
Pace Analytical



Scott Lindsay
Group Leader

PACE ANALYTICAL
BULK SAMPLE ANALYSIS REPORT

NVLAP Accredited
 NVLAP Code Number 101265-00

Date: June 7, 1998

Client: Alliance Indiana, Inc.

Project Identification: NGR-07A01 - New Wahington H.S. - Ag Building
 Date Sample Received: June 4, 1998
 Pace Lab Batch Number: 980927

Lab ID	Client ID	Color / Description	Layer(s)	Asbestos Type	%	Other Fibrous Material	%	Non-Fibrous Material
001	SWCT-1	White Ceiling Tile	2	Chrysotile	3-5	Glass	50-60	Paint Binder
002	SWCT-2	White Ceiling Tile	2	All Layers No Asbestos Detected		Cellulose Glass	30-40 30-40	Perlite Paint
003	SRCT	White Ceiling Tile	2	All Layers No Asbestos Detected		Cellulose Glass	30-40 30-40	Perlite Paint
004	BRCT	White Ceiling Tile	2	All Layers No Asbestos Detected		Cellulose Glass	30-40 30-40	Perlite Paint
005	SECT	White Ceiling Tile	2	All Layers No Asbestos Detected		Glass	70-80	Paint Binder
006	SRFT	Tan Floor Tile	1	Chrysotile	3-5	None Detected		Binder
007	SRFT-M	Black Mastic	1	Chrysotile	5-10	None Detected		Adhesive
008	BRFT	Tan Floor Tile	1	Chrysotile	2-3	None Detected		Binder

- Analytical Methods: EPA 600/M4-82-020, December 82, EPA 600/R-93/116, July 1993
- Enclosed test results relates only to items tested.
- This report shall not be reproduced, except in full without written approval of the laboratory.
- This report can not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
- Method limitations: Analysis of floor tile and other resinously bound materials by Polarized Light Microscopy (PLM) may yield false negative results due to method limitations. In these cases Pace recommends alternative methods of analysis.
- For all heterogeneous samples easily separated into sub-samples each component will be analyzed separately. When layers cannot be separated without compromising the layer they will be analyzed as one sample. When a heterogeneous sample contains no asbestos in any layer reported results will be combined into one. When asbestos is detected in a layer or layers of a heterogeneous sample each individual layer will be reported separately.


PACE ANALYTICAL
BULK SAMPLE ANALYSIS REPORT
 NVLAP Accredited
 NVLAP Code Number 101265-00

Date: June 7, 1998


Client: Alliance Indiana, Inc.

Project Identification: NGR-07A01 - New Wahington H.S. - Ag Building
 Date Sample Received: June 4, 1998
 Pace Lab Batch Number: 980927

Lab ID	Client ID	Color / Description	Layer(s)	Asbestos Type	%	Other Fibrous Material	%	Non-Fibrous Material
009	BRFT-M	Black Mastic	1	Chrysotile	5-10	None Detected		Adhesive
010	SEFT	Tan Floor Tile	1	Chrysotile	3-5	None Detected		Binder
011	SEFT-M	Black Mastic	1	Chrysotile	5-10	None Detected		Adhesive



 Craig Nixon, Analyst



 Scott Lindsay, Group Leader

- Analytical Methods: EPA 600/M4-82-020, December 82, EPA 600/R-93/116, July 1993
- Enclosed test results relates only to items tested.
- This report shall not be reproduced, except in full without written approval of the laboratory.
- This report can not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.
- Method limitations: Analysis of floor tile and other resinously bound materials by Polarized Light Microscopy (PLM) may yield false negative results due to method limitations. In these cases Pace recommends alternative methods of analysis.
- For all heterogeneous samples easily separated into sub-samples each component will be analyzed separately. When layers cannot be separated without compromising the layer they will be analyzed as one sample. When a heterogeneous sample contains no asbestos in any layer reported results will be combined into one. When asbestos is detected in a layer or layers of a heterogeneous sample each individual layer will be reported separately.

980927

ALLIANCE INDIANA, INC.
 1433 Sadlier Circle West Dr.
 Indianapolis, IN 46239
 317/351-5600 Fax 317/351-5610

Project Name- Ag Building
 Project Location- New Washington High School
 City/State- New Washington, Indiana
 Project Number- NGR07A01 Date- 2 June 98
 Samples Collected By- Karen Fox

SAMPLE I.D. NUMBER	LOCATION OF SAMPLE	DESCRIPTION OF SAMPLE MATERIAL
SWCT-1	Southwest Room	Ceiling Tile - Squiggly ^{chry} 3-5
SWCT-2	Southwest Room	Ceiling Tile - Pin Hole ^{chry} N/A
SRCT	Small Restroom	Ceiling Tile N/A
BRCT	Big Restroom	Ceiling Tile N/A
SECT	Southeast Room	Ceiling Tile N/A
SRFT	Small Restroom	Floor Tile ^{chry} 3-5
SRFT-M	Small Restroom	Mastic underneath ^{sample chry} SRFT-5-10
BRFT	Big Restroom	Floor Tile ^{chry} 2-3
BRFT-M	Big Restroom	Mastic underneath ^{sample chry} BRFT-5-10
SEFT	Southeast Room	Floor Tile ^{chry} 3-5
SEFT-M	Southeast Room	Mastic underneath ^{sample chry} SEFT-5-10

CHAIN OF CUSTODY

Sample By: KAREN FOX
 Date: 2 June 98
 Signature: Karen Fox
 Date Shipped: 3 June 98

Received By: P. Priddy
 Date: 6/3/98
 Signature: _____
 Shipped Via: _____

Recorded By: _____
 Date: 6/4/98 Log#: 910
 Signature: [Signature]
 Shipped To: _____

Pace Analytical

June 20, 1998

Karen Foxx
Alliance Indiana, Inc.
1433 Sadlier Circle, West Drive
Indianapolis, IN 46239

RE: One PLM Point Count Analysis
Client Project Name: New Washington H.S.
Client Project Number: NGR-07A01
Pace Project Number: 370008
Laboratory Batch Number: A-980927


Dear Ms. Foxx:

Enclosed is the result of the bulk asbestos analysis for the one sample which was submitted to the Pace Analytical Asbestos Laboratory on June 4, 1998. The methodology employed to obtain these results was the EPA 600/R-93/116, July 1993 in Bulk Insulation Samples. Percentage of Asbestos was determined using the point count procedure.

Pace will hold your samples for 30 days after the completion of the analysis. At the end of the 30 day period, it will be our policy to dispose of the samples unless prior arrangements are made.

It has been a pleasure serving you and if there are any questions, please contact me at (317) 849-4990.

Respectfully submitted,
Pace Analytical



Scott Lindsay
Industrial Hygiene Group Leader

SL/lt

Pace Analytical
Point Count Analysis Report
NVLAP Number 101265-00

DATE: June 22, 1998

CLIENT: Alliance Indiana, Inc.


PROJECT IDENTIFICATION: New Washington H.S. -NGR-07A01
DATE RECEIVED: June 4, 1998
PACE LAB BATCH NUMBER: 370008

<u>Sample ID</u>	<u>Sample Description</u>	<u>Percent Asbestos</u>	<u>Type(s) of Asbestos</u>
SWCT-1	White Ceiling Tile	3	Chrysotile


Analytical Method: EPA-600/R-93/116, July 1993
Analytical Instrument: Olympus Polarizing Microscope BHTP-2
Sample Homogenized
NVLAP Accredited Bulk Asbestos Quality Assurance Program
Percentages determined using Point Count Procedure
Test Report Relates Only To Item Tested
Report Cannot Be Used To Claim Product Endorsement

Analyst: Craig Nixon

Signature



Respectfully submitted,
Pace Analytical


Environmental/Analytical Testing Division

**ANNUAL NOTIFICATIONS
ACCREDITATIONS
TRAINING
INFORMATION**

Indiana Department of Environmental Management
100 N. Senate Avenue
Mail Code 61-52 IGCN 1003
Indianapolis, IN 46204-2251



April 17, 2014

RECEIVED APR 22 2014

Benjamin S. Hood
Alliance Environmental Group
5340 Commerce Circle, Ste E
Indianapolis IN 46237

Re: Asbestos Inspector # 19A001039

Based upon the review of your license application, the Office of Air Quality has determined that you have fulfilled the requirements of 326 IAC 18 and are eligible for licensing in the following discipline:

Asbestos Inspector

Your Asbestos Inspector license is attached below. The license is waterproof and tear resistant. Please sign your license and do not laminate or alter your license in anyway. Your license must be available for review at all times while implementing an asbestos project. This license may be revoked, pursuant to 326 IAC 18-1-7, if you:

- (1) Violate any requirements of these rules (326 IAC 18), 326 IAC 14-10, or any requirement of the Asbestos-Containing Materials in Schools Rule or any other federal, state, or local regulation pertaining to asbestos in buildings or to asbestos projects.
- (2) Falsify information on your application for licensing.
- (3) Fail to meet any qualifications specified in 326-IAC 18-1-4.
- (4) Conduct asbestos project, or related asbestos handling activity, in a manner which is hazardous to the public health.

Your license is valid effective 05/05/2014, and will expire on 05/05/2015, as indicated on your card. We suggest that you attend the required training and submit an application for license renewal early to insure your license does not lapse. NOTE: 326 IAC 18-1-4(h) and 326 IAC 18-1-6(e) require that any individual who has an eighteen (18) month lapse between any two training courses of the same discipline to attend an initial training course for the discipline in which they are seeking a license. In order to avoid re-taking the initial training course you must have attended a refresher in the discipline you are seeking a license within eighteen (18) months from the date of issuance of your last training course certificate.

Office of Air Quality, Asbestos Licensing Section (317) 233-3861



Indiana Dept. of Environmental Management

Benjamin S. Hood

Asbestos Inspector License #: 19A001039

Effective: 05/05/2014	Expiration: 05/05/2015
Birth Date: 04/10/1978	Gender: M
Height: 6-00	Eye Color: Brown
Weight: 285	Hair Color: Brown

NOTICES

NOTIFICATION LOG

LEA Name - Greater Clark County Schools

<u>Date of Notification</u>	<u>Copy of Notification in Supplemental Book?</u>
1989	
1990	
1991	
1992	
1993	
1994	
1995	✓
1996	✓
1997	✓
1998	✓
1999	✓
2000	✓
2001	✓
2002	✓
2003	✓
2004	✓
2005	✓
2006	✓
2007	✓
2008	✓

March 2015

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services at River Valley Middle School, which is located at 2220 Veteran's Parkway, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, Service Center, Corden Porter Storage, Auto Tech Program- Witten Property, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2015/2016 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

* The required triennial re-inspection will be performed in April 2016.

* The required six month periodic surveillance was performed in October 2014.

* The required six month periodic surveillance activities are scheduled for April and October each year.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Corden Porter former Options Building and the Administration Building

March 2014

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2220 Veteran's Parkway, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, Corden Porter Storage, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2014/2015 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

* The required triennial re-inspection will be performed in April 2013.

* The required six month periodic surveillance was performed in October 2013.

* The required six month periodic surveillance activities are scheduled for April and October each year.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

March 2013

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, Corden Porter Storage, and Corden Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2013/2014 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

- * The required triennial re-inspection will be performed in April 2013.
- * The required six month periodic surveillance was performed in October 2012.
- * The required six month periodic surveillance activities are scheduled for April and October each year.
- * Projects completed in 2012: Parkview Middle School.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

March 2012

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763, Subpart E, Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the initial inspection, triennial reinspections, and 6 month periodic surveillance of asbestos-containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the plans should contact the individual school office. Master copies of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxiliary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Greater Clark County Schools, school facilities, and buildings which contain asbestos-containing materials (ACMs) and must comply with the 40 CFR 763, Subpart E (AHERA) regulations include:

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools, the Auxiliary Services Building, Service Center, and Cordon Porter Center with Gym.

Listed is a brief description of asbestos projects currently ongoing and completed at our facilities this past school year, as well as activities currently scheduled for the 2012/2013 school year. Detailed reports of each activity will become a part of each school's asbestos management plan and may be reviewed in the school office.

- * The required triennial re-inspection will be performed in June 2013.
- * The required six month periodic surveillance was performed in December 2011.
- * The required six month periodic surveillance activities are scheduled for June and December each year.
- * Projects completed in 2011: Options building and Parkwood Elementary.
- * Projects scheduled for 2012: Parkview Middle School and Bridgepoint Elementary.
- * Cordon Porter storage building was sold in 2012.

School facilities and buildings that are asbestos free and require no surveillance or reinspection are:

Pleasant Ridge Elementary School, Utica Elementary School, Cordon Porter former Options Building and the Administration Building

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxillary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, Options and Corden Porter Center Buildings and Alternative School-

- * The required triennial reinspection will be performed in June 2013.
- * The required six month periodic surveillance was performed in December 2010.
- * The next scheduled activity is the required six month periodic surveillance in June 2011.
- * Charlestown High School asbestos removal project was completed in 2010.
- * Options Building is under renovation in 2011.
- * Parkwood Elementary is under renovation in 2011.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building
– These buildings are asbestos free and **Riverside Elementary** was demolished in 2006.
No surveillances or reinspections are required for these buildings.

March 2011

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Auxillary Services building, which is located at 2710 E 10th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

* The required triennial reinspection will be performed in June 2010.

* The required six month periodic surveillance was performed in December 2009.

* The next scheduled activity is the required six month periodic surveillance in December 2010.

Charlestown High School is an ongoing asbestos removal project which will be complete prior to partial demolition.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building –
These buildings are asbestos free and Riverside Elementary was demolished in 2006.
No surveillances or reinspections are required for these buildings.

March 2010

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E Asbestos Containing Materials in Schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number (812) 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown and New Washington High Schools; Parkview, River Valley and Charlestown Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required triennial reinspection was performed in June 2007.
- * The required six month periodic surveillance was performed in December 2008.
- * The next scheduled activities are the required six month periodic surveillance in June 2009 and Dec 2009. Charlestown High School has undergone an asbestos removal project prior to partial demolition.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building – These buildings are asbestos free and **Riverside Elementary** was demolished in 2006. No surveillances or re-inspections are required for these buildings.

April 2009

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number (812)288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Hobgood at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required triennial reinspection was performed in June 2007.
- * The required six month periodic surveillance was performed in December 2007.
- * The next scheduled activities are the required six month periodic surveillance in June 2008 and Dec 2008.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building – These buildings are asbestos free. **Riverside Elementary** was Demolition in 2006. No surveillances or reinspections are required.

April 2008

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Chuck Graves at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

* The required six month periodic surveillance was performed in June 2006.

* The required six month periodic surveillance was performed in December 2006.

* The next scheduled activities are the required six month periodic surveillance in June 2007 and Dec 2007.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building – These buildings are asbestos free. **Riverside Elementary** was Demolition in 2006. No surveillances or reinspections are required.

March 2007

AHERA ANNUAL NOTICE
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Chuck Graves at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

* The required triennial reinspection was performed in June 2005.

* The required six month periodic surveillance was performed in December 2005.

* The next scheduled activities are the required six month periodic surveillance in June 2006 and Dec 2006.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building –
These buildings are asbestos free. No surveillances or reinspections are required.

March 2006

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Chuck Graves at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required triennial reinspection was performed in June 2004.
- * The required six month periodic surveillance was performed in December 2004.
- * The next scheduled activities are the required six month periodic surveillance in June 2005 and December 2005.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building -

- * These buildings are asbestos free. No surveillances or reinspections are required.

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Tony Nauert at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required six month periodic surveillance was performed in June 2003.
- * The required six month periodic surveillance was performed in December 2003.
- * The next scheduled activities are the required triennial reinspection in June 2004 and a required six month periodic surveillance in December 2004.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building -

- * These buildings are asbestos free. No surveillances or reinspections are required.

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Tony Nauert at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the former Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required six month periodic surveillance was performed in June 2002.
- * The required six month periodic surveillance was performed in December 2002.
- * The next scheduled activity is the required periodic surveillance in June 2003.

Pleasant Ridge Elementary School, Utica Elementary School and the (New) Administration Building -

- * These buildings are asbestos free. No surveillances or reinspections are required.

May 2003

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Tony Nauert at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the Administration Building, Service Center, and Corden Porter Center Buildings -

- * The required triennial reinspection was performed in July 2001.
- * The required six month periodic surveillance was performed in December 2001.
- * The next scheduled activities are the required periodic surveillances in June 2002 and December 2002.

Pleasant Ridge Elementary School and (New) Utica Elementary School -

- * These buildings are asbestos free. No surveillances or reinspections are required.

(Old) Utica Elementary School -

- * In accordance with information collected from the GCCS this building has been deeded to the town of Utica. No further AHERA periodic surveillances or triennial reinspections will be conducted by the designated person.

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Tony Nauert at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, (Old) Utica, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the Administration Building, Service Center, and Corden Porter Center -

- * The required six month periodic surveillance was performed in June 2000.
- * The required six month periodic surveillance was performed in January 2001.
- * The next scheduled activity is a required triennial reinspection in June 2001.

Pleasant Ridge Elementary School and (New) Utica Elementary School -

- * This building is asbestos free. No surveillances or reinspections are required.

June 2001

AHERA Annual Notice
GREATER CLARK COUNTY SCHOOLS

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Tony Nauert at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

Jeffersonville, Charlestown, and New Washington High Schools; Parkview, Charlestown, and River Valley Middle Schools; Wilson, Thomas Jefferson, Northaven, Utica, New Washington, Jonathan Jennings, Bridgepoint, Maple, Riverside, Spring Hill, and Parkwood Elementary Schools; the Administration Building, Service Center, and Corden Porter Center -

- * The required six month periodic surveillance was performed in June 1999.
- * The required six month periodic surveillance was performed in December 1999.
- * The next scheduled activity is a required periodic surveillance in June 2000.

Pleasant Ridge Elementary School -

- * This building is asbestos free. No surveillances or reinspections are required.

June 2000

ASHERA Annual Notice

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "ASHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Meredith at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

All school and support buildings where it is required -

- * The required six month periodic surveillance was performed in June 1998.
- * The required six month periodic surveillance was performed in December 1998.
- * The next scheduled activity is a required periodic surveillance in June 1999.

Parkwood Elementary School

- * O & M was performed in the boiler room in May 1998.

AHERA Annual Notice

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Meredith at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

All school and support buildings where it is required -

- * The required periodic surveillance was performed in June 1997 and December 1997.
- * Next activity scheduled activity is a required third year reinspection in June 1998.

AHERA Annual Notice

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available, should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Steve Meredith at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

All school and support buildings where it is required -

- * The required periodic surveillance was performed in June 1996 and December 1996.
- * The next required periodic surveillance will be performed in June 1997 and December 1997.

June 97

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Denny Johanson at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

All buildings where it is required -

- * The required third year reinspection was performed in June 1995.
- * The required periodic surveillance was performed in December 1995.
- * Next activity scheduled is a periodic surveillance in June 1996.

Charlestown High School -

- * Transite panels were compliantly removed from the exterior of the building.

Corden Porter Building #3 -

- * TSI was compliantly removed from the boiler room.

June 96

This information is being published to comply with the requirements of 40 CFR 763 Subpart E asbestos containing materials in schools. This regulation, commonly known as the "AHERA" rule, requires local education agencies, such as this one, to perform certain tasks in regards to the presence and control of asbestos containing materials in the buildings under the jurisdiction of the local education agency.

These include but are not limited to:

1. Developing an asbestos management plan which is designed to outline procedures and guidelines for the inspection, reinspection and periodic surveillance of asbestos containing materials that are present in the buildings.
2. Provide awareness training and additional training to selected school employees.
3. Periodically notify all workers and occupants, or their local guardians, parent teacher organizations, and collective bargaining organizations of the availability of asbestos management plans, the location of same and the times that the plans may be reviewed.

This notification is to advise all patrons, occupants, or their legal guardians, collective bargaining organizations, and parent-teachers organizations, that the asbestos management plans required under this act are available for review upon request. A copy of the plans for all buildings under the jurisdiction of this local education agency are available in the Service Center building, which is located at 301 E. 11th Street, Jeffersonville, Indiana 47130; telephone number 288-4821. Plans for individual schools and other buildings are located in the administration office of each school. The plans can be viewed by any person during normal business hours of the particular school. Interested parties wishing to inquire about the hours and times that the plans are available, should call the above number.

At this time, the management plans can provide information regarding inspections, response actions, and post-response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Inquiries regarding any facet of the regulation or the management plans should be directed to Mr. Dennis Johanson at the above telephone number during regular business hours.

Listed is a brief description of asbestos work that has been completed in our schools this year. Detailed reports have become part of each school's asbestos management plan and may be reviewed in the school office.

All school and support buildings where it is required -

- * The required periodic surveillance was performed in June 1995 and December 1995.
- * The required triennial reinspection was performed in June 1995.
- * The next required periodic surveillance will be performed in June 1996 and December 1996.

June 95

ACCREDITATIONS



Environmental Management Institute

5610 Crawfordsville Road, Suite 15, Indianapolis, Indiana 46224-3714

317/248-4848 • 800/488-8842 • FAX 317/248-4846
www.envtlmgmt.org

This confirms that

Sandy Shadley

Completed the Required Initial Training for
Asbestos Accreditation Under TSCA Title II
and has
passed with a Score of 70 or Greater the Examination for

Asbestos Management Planner

Course Date
December 10 - 11, 2009

Examination Date
December 11, 2009



Jack E. Leonard, President

Certificate: MP(I) 2248
Expires: December 11, 2010

Approved by:: Illinois Department of Public Health
Indiana Department of Environmental Management

Indiana Department of Environmental Management
100 N. Senate Avenue
Mail Code 61-52 IGCN 1003
Indianapolis, IN 46204-2251



January 21, 2010

RECEIVED JAN 23 2010

Sandra S. Shadley
Alliance Environmental Grp
5340 Commerce Circle Ste E
Indianapolis IN 46237

Re: Asbestos Management Planner # 19A002720

Based upon the review of your license application, the Office of Air Quality has determined that you have fulfilled the requirements of 326 IAC 18 and are eligible for licensing in the following discipline:

Asbestos Management Planner

Your Asbestos Management Planner license is attached below. The license is waterproof and tear resistant. Please sign your license and do not laminate or alter your license in anyway. Your license must be available for review at all times while implementing an asbestos project. This license may be revoked, pursuant to 326 IAC 18-1-7, if you:

- (1) Violate any requirements of these rules (326 IAC 18), 326 IAC 14-10, or any requirement of the Asbestos-Containing Materials in Schools Rule or any other federal, state, or local regulation pertaining to asbestos in buildings or to asbestos projects.
- (2) Falsify information on your application for licensing.
- (3) Fail to meet any qualifications specified in 326-IAC 18-1-4.
- (4) Conduct asbestos project, or related asbestos handling activity, in a manner which is hazardous to the public health.

Your license is valid effective 01/21/2010, and will expire on 01/21/2011, as indicated on your card. We suggest that you attend the required training and submit an application for license renewal early to insure your license does not lapse. NOTE: 326 IAC 18-1-4(h) and 326 IAC 18-1-6(e) require that any individual who has an eighteen (18) month lapse between any two training courses of the same discipline to attend an Initial training course for the discipline in which they are seeking a license. In order to avoid re-taking the initial training course you must have attended a refresher in the discipline you are seeking a license within eighteen (18) months from the date of issuance of your last training course certificate.

Office of Air Quality, Asbestos Licensing Section (317) 233-3861



Indiana Dept. of Environmental Management

Sandra S. Shadley

Asbestos Management Planner License #: 19A002720

Effective: 01/21/2010	Expiration: 01/21/2011
Birth Date: 04/21/1959	Gender: F
Height: 5-08	Eye Color: Blue
Weight: 140	Hair Color: Brown

ENVIRONMENTAL SAFETY ASSURANCE INSTITUTE
1435 Sadlier Circle West Drive
Indianapolis, Indiana 46239
(317) 352-1270 / (317) 352-06

GEORGE W^M (BILL) OGLE
312 - 52 - 2526

Has Successfully Completed The Course
Required Under TSCA Title II
And Passed The Written Examination
With a Score of 70% or Better
For

**ASBESTOS MANAGEMENT PLANNER
REFRESHER**

Accredited by the
Indiana Department of Environmental Management.

Certificate # ES04/MPR058

Course Dates: 09/29/2004
Test Date: 09/29/2004 Expires: 09/29/2005



Sharyn Reyes
Sharyn Reyes
Instructor

ENVIRONMENTAL SAFETY ASSURANCE INSTITUTE
1435 Sadler Circle West Drive
Indianapolis, Indiana 46239
(317) 352 -1270 / (317) 352 - 0669

CHRISTIAAN SPARKS
306 - 04 - 2616

Has Successfully Completed The Course
Required Under TSCA Title II
And Passed The Written Examination
With a Score of 70% or Better

For
ASBESTOS BUILDING INSPECTOR REFRESHER

Accredited by the
Indiana Department of Environmental Management.

Certificate # ES03/BIR755

Course Dates: 09/26/2003
Test Date: 09/26/ 2003 Expires: 09/26/2004



Sharyn Reyes
Sharyn Reyes
Instructor / Manager

ENVIRONMENTAL SAFETY ASSURANCE INSTITUTE
1435 Sadler Circle West Drive
Indianapolis, Indiana 46239
(317) 352-1270 / (317) 352-06

GEORGE Wm. (BILL) OGLE

Has Successfully Completed The Course
Required Under TSCA Title II
And Passed The Written Examination
With a Score of 70% or Better
For

**ASBESTOS MANAGEMENT PLANNER
REFRESHER**

Accredited by the
Indiana Department of Environmental Management.

Certificate # ES03/MPR045

Course Dates: 09/05/2003
Test Date: 09/05/2003 Expires: 09/05/2004



Sharyn Reyes
Sharyn Reyes
Instructor

ENVIRONMENTAL SAFETY ASSURANCE INSTITUTE
1435 Sadlier Circle West Drive
Indianapolis, Indiana 46236
(317) 352-1270 / (317) 352 - 0669

PATRICK E. WILSON
309 - 90 - 6909


Has Successfully Completed The Course
Required Under TSCA Title II
And Passed The Written Examination
With a Score of 70% or Better
For

ASBESTOS BUILDING INSPECTOR REFRESHER

Accredited by the
Indiana Department of Environmental Management.

Certificate # ES00/BIR482

Course Dates: 11/29/2000
Test Date: 11/29/2000 Expires: 11/29/2001


Sharyn Reyes
Instructor



Environmental Management Institute

5610 Crawfordsville Road, Suite 15, Indianapolis, Indiana 46224-3714

317/248-4848 • 800/488-8842 • FAX 317/248-4846

www.spea.iupui.edu/Envtl_mgmt

This confirms that

George Wm. (Bill) Ogle



Completed the Requisite Initial Training for
Asbestos Accreditation Under TSCA Title II
and has
Passed with a Score of 70 or Greater the Examination for
Asbestos Management Planner

Course date
March 2 - 3, 2000

Examination Date
March 3, 2000

Jack E. Leonard, President

Certificate: MP(I) 2157
Expires March 3, 2001

Approved by: Illinois Department of Public Health
Indiana Department of Environmental Management



ENVIRONMENTAL SAFETY ASSURANCE INSTITUTE
1435 Sadlier Circle West Drive
Indianapolis, Indiana 46239
(317) 352-1270 / (317) 352-0669

CLINT YATES

316 - 92 - 7065

Has Successfully Completed The Course
Required Under TSCA Title II
And Passed The Written Examination
With a Score of 70% or Better
For

ASBESTOS BUILDING INSPECTOR REFRESHER

Accredited by the
Indiana Department of Environmental Management.

Certificate # ES/BIR98/004.

Course Dates: 01/22/98 - 01/22/98
Test Date: 01/22/98 Expires: 01/22/99

Sharyn Reyes

Sharyn Reyes
Assistant / Instructor

Environmental Management Institute

Environmental and Occupational Training Service

5610 Crawfordsville Road, Suite 15

Indianapolis, Indiana 46224-3714

317/248-4848

This confirms that

Rex Gaddis


Completed the Requisite Refresher Training for
Asbestos Accreditation Under TSCA Title II
and has

Passed with a Score of 70 or Greater the Examination for

Asbestos Building Inspector

Course date
November 22, 1994

Examination Date
November 22, 1994



Jack E. Leonard, President

Certificate: IN(R) 2713
Expires November 22, 1995

Approved by: Illinois Department of Public Health
Indiana Department of Environmental Management

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
ASBESTOS CERTIFICATE OF ACCREDITATION
CERTIFICATE # 192248025 EXPIRATION DATE 2/18/96
Rex Gaddis
IS CERTIFIED IN THE FOLLOWING DISCIPLINE(S)
INSPECTOR PLANNER DESIGNER
SUPERVISOR WORKER
WASTE DISPOSAL MANAGER
BIRTHDATE: 3/24/52 SEX: M EYES: BLU
HEIGHT: 5-10 WEIGHT: 220 HAIR: BRO

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT
ASBESTOS CERTIFICATE OF ACCREDITATION
CERTIFICATE # 190908032 EXPIRATION DATE 3/16/96
Rex Gaddis
IS CERTIFIED IN THE FOLLOWING DISCIPLINE(S)
INSPECTOR PLANNER DESIGNER
SUPERVISOR WORKER
WASTE DISPOSAL MANAGER
BIRTHDATE: 3/24/52 SEX: M EYES: BLU
HEIGHT: 5-10 WEIGHT: 220 HAIR: BRO

TRAINING

**OPERATIONS AND MAINTENANCE
INFORMATION**

MINOR FIBER RELEASE EPISODE

The local education agency shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., the falling or dislodging of not more than 3 square or linear feet of friable ACBM):

1. Thoroughly saturate the debris using wet methods.
2. Clean the area using wet methods, protective clothing, HEPA-vacuums, mini-enclosures, glove bags, as necessary to inhibit the spread of any released fibers. At a minimum, workers should use air-purifying respirators with HEPA filters.
3. Place the asbestos debris in a sealed, leak-tight container, preferably a 6 mil. labeled plastic bag.
4. Repair the area of damaged ACM with materials such as asbestos-free spackling, plaster, cement, or insulation, or seal with latex paint or an encapsulant, or immediately have the appropriate response action implemented.
5. Each fiber release episode should be documented.

MAJOR FIBER RELEASE EPISODE

The local education agency shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., the falling or dislodging of more than 3 square or linear feet of friable ACBM):

1. Restrict entry into the area and post signs to prevent entry into the area by persons other than those necessary to perform the response action.
2. Shut off or temporarily modify the air-handling system to prevent the distribution of fibers to other areas in the building.
3. AHERA requires that major fiber release episodes be designed by accredited Project Designers. However, the following response procedures should form the basis for response actions.
4. All the procedures recommended by EPA and required by OSHA for large-scale removal of ACM should be used. These include containment barrier, negative pressure ventilation, personal respiratory protection and protective clothing, decontamination facilities, and air testing.
5. Workers should wear "type C" respirators and protective clothing, including a body suit, hood, boots and gloves. Personal air monitoring may be conducted on representative workers, but is not required by OSHA when "type C" respirators are used.
6. Fallen debris should be sprayed with amended water and placed in plastic bags for disposal. Shovels are useful for collecting the debris. The floor should be thoroughly cleaned with a HEPA vacuum cleaner.
7. Walls, ceiling, pipes, boilers, or other surfaces where ACM was damaged or delaminated should be repaired temporarily. This might involve replastering with asbestos-free material, spraying with an encapsulant, or taping with duct tape. In some cases, ACM beyond the immediate area of damage may need to be removed to prevent additional episodes.
8. The air should be tested for asbestos fibers before the plastic barriers are removed and the area reoccupied. Testing should follow guidelines in Chapter 6 of the Purple Book and Chapter 4 of the Silver Book. That is, air should be sampled at the specified number of locations and analyzed by either phase contrast microscopy or transmission electron microscopy. However, sampling should not be done aggressively since the use of blowers and fans may dislodge fibers from the remaining ACM.

9. After the barriers have been taken down, a decontamination of the entire building or a portion of it should be considered. The need for this will depend on how rapidly the response team reacted to the episode and, in particular, how quickly the HVAC system was turned off. A thorough decontamination includes HEPA-vacuuming and/or wet wiping all carpets, furniture, and other surfaces. Decontamination of the HVAC system would involve disassembling and cleaning (HEPA-vacuuming or wet wiping) ducts, ventilators, registers, and other system parts. System filters should also be removed and replaced.

10. All equipment used in the cleanup operation should be washed or wiped with damp cloths. All disposable materials (e.g., cloths, mop heads, filters, coveralls) should be discarded as asbestos wastes.

11. Each fiber release episode should be documented.

OPERATIONS AND MAINTENANCE REPORT
(Use only for O&M work less than 3 square or 3 linear feet)

L.E.A.: _____

BUILDING: _____

DATE: _____

The following information is provided in accordance with 40 CFR 763.91 and 763.94.

1. Location: _____

Homogeneous Area/Material Description _____

2. Response: Clean _____ Repair _____ Encapsulation _____

Enclosure _____ Removal _____

Reason: _____

3. Work Description: _____

4. Date: Start _____ Stop _____

Time: Start _____ Stop _____

5. Material: Surface _____ SF Thermal _____ LF

Other: _____ SF or _____ LF

6. Asbestos Control Method: Wet Methods _____ HEPA Vacuum _____

Glovebag _____ Mini-Enclosure _____

7. Respiratory Protection: N.A.P.R. _____ P.A.P.R. _____

Were all employees properly fit tested? YES NO NOT APPLICABLE

**REMOVAL PROJECT
INFORMATION**

SHORT TERM WORKER PROGRAM

GREATER CLARK COUNTY SCHOOLS

SHORT-TERM WORKER SIGN OFF SHEET

This form should be signed each and every time before a "short-term worker" (telephone repair worker, utility worker, etc.) performs work that may cause him to come in contact with ACBM or suspected ACBM assumed to be ACM. One copy of this form should then be forwarded to the LEA designated person, and one copy should be maintained in the school building's copy of the supplemental binder provided by Alliance Indiana, Inc., in order to fulfill the LEA's recordkeeping requirements. The third copy should be forwarded to Alliance Indiana, Inc. for placement in its copy of the supplemental binder.

School Building Name - New Washington High School Date _____

I certify that before performing any work which would possibly cause me to come in contact with Asbestos Containing Building Materials (ACBM), I was provided with adequate information regarding the locations of ACBM and suspected ACBM assumed to be ACM in the above-mentioned school building where I performed the work.

Signature - _____

Company - _____

Description of work (including number of days on site) - _____
